



JD'S PLANE REPAIR, LLC

12106 FM 400, SLATON, TX 79364

HANGER #10

PH: 432-788-7137

WWW.JDPLANEREPAIR.COM

4-27-18

N11312

Electric fuel pump and hand wobble pump ops check with no defects noted. Fuel selector ops check with no defects noted.

Jonathan Siemens, A&P IA

Director: Texas Air Museum
Malcolm Laing

04-14-2018

It the course of recovering the Sonia 51 replica from impact site outside of Columbia Tenn, several safety measures were undertaken prior to disassembly.

1. Battery was disconnected.
2. Fuel was drained from the aircraft, the firewall connection was unscrewed and fuel drained at that point, the fuel selector valve was operated and there was free flow from both tanks, also there was fuel back from the carburetor.

If you have further questions, please feel free to contact me.

Sincerely Yours

Thad Dulin, A&P

