

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
------	--------------------------------	---------------------------------------	---

TOTAL brought forward from previous page

5-24-2016

N 87266

ACTT 9193.0

1 Installed new tire on RT main wheel.

2 Replaced cam lock in both ENG cowlings

3 Replaced working rivets on RT inboard wheel well door check door closer when during gear retraction test, no problem found.

4 C/W AD 2000-01-16 Para B on both ENG exhaust system. No issue found. Next inspection due 9243,

5 Installed New battery in the aircraft.

6 Lube aircraft as required.

7 Serviced wheel bearing with grace.

8 Check that all AD were in Compliance.

9C/W Far: 91 207 Para d. Sent ELT out for New Batterys and was recertify.

I certify that this Aircraft has been inspected IAW a Cessna 402 100 HR annual inspection and was determined to be in an Airworthy Condition.

Signature: _____

Certificate #: _____

SUB-TOTAL this page

TOTAL-Carry forward to next page

[illegible]



104 Grafton Drive Portsmouth New Hampshire 03801
Phone: 603 430 1111 Toll Free: 888 732 7324

fax: Maintenance and Avionics 603 430 1199, fax: Operations 603-776-0266

DATE	TOTAL TIME IN SERVIC
------	-------------------------------

8/2/12 N87266 Cessna 402B S/N 402B1097 Hobbs 7025.8 W/O 6218

RH Engine

Removed, cleaned and gapped spark plugs.

Replaced 7 spark plugs with new P/N RHB32E.

Ground run, leak and operational check good.

The aircraft and/or components identified above were repaired in accordance with current FAR'S as well as manufacturers recommendations and is approved for return to service.

Authorized Signature Travis Buchanan

ANNUAL INSPECTION

15 OCTOBER 2013 N87266 CESSNA 402B SN/402B1097

RIGHT ENGINE CONTINENTAL TSIO-520-EB SN/ 815017-R

REPLACED OIL AND FILTERS WITH 10 QUARTS OF PHILLIPS 20w50 X/C AND CH481081.OILFILTER.

C/W AD 2000-01-16 PARAGRAPH B ON ENGINE EXHAUST SYSTEM, NO ISSUES FOUND.
I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED I.A.W. A 100 HOUR / ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

A&P

5/24/16

Engine# 2 Cont Model TSIO-520-EB SN 815017-R TSO: 920'2

- 1 Comp check #1 70/80 #2 60/80, #3 68/70, #4 68/80, #5 72/80, #6 67/80.
- 2 C/W Ad 2009-16-03 perform leak found no leaks.
- 3 Clean spark plugs and tested, set gaps.
- 4 Changed oil and filter serviced with Phillips 20-50 X/C.
- 5 CW AD 2000-01-16 para b. Eng Exhaust sys. No issues found.

I certify that this ENG has been inspected IAW 100 Hr Annual inspection and was determined to be in an airworthy condition.

Signature:

Certificate#

SUB-TOTALS this page

TOTALS—Carry forward to next page

