



Photo 1 –View of fuselage revealing buckling damage (Courtesy of FAA)



Photo 2 – View of empennage buckling (Courtesy of FAA)



Photo 3 – View of airplane and separated main landing gear (Courtesy of the FAA)