



SBI AIRCRAFT SERVICES
LACONIA AIRPORT (KLCI)
[REDACTED]
2017 [REDACTED]
Date: 08/15/2016 N221EZ Tach 670.7
TTE 670.7

Performed an annual condition inspection I/AW FAR 43 appendix D. Ran engine for warm up and ops check. Oil and filter changed by owner. Cut open used oil filter for internal inspection and found normal. Performed air differential check on all cylinders with findings as follows. Cylinder #1=80/78 #2=80/78 #3=80/79 #4=80/78. Engine oil and filter previously changed by owner/pilot. Cut used oil filter open for internal inspection and found normal. Visually inspected all engine controls and operations and found ok. Ran engine for leak and ops check and found satisfactory.

I certify that this Engine has been inspected on August 14, 2017 in accordance with the manufacturers maintenance and inspection procedures and was found to be in a condition for safe operation

A&P [REDACTED]

Photo 1 – Last Condition Inspection - Engine

YE DA

SBI AIRCRAFT SERVICES
LACONIA AIRPORT (KLCI)
[REDACTED]

Date: 08/15/2016 N221EZ Tach 670.7
TTAF 670.7 2017 [REDACTED] [REDACTED]

Performed an annual condition inspection I/AW FAR 43 appendix D. Checked all flight controls for operation and lubrication. Lubed all movable attachment points, hinges, pulleys and control levers. Checked condition of aircraft covering and brace components and attachments. Visually inspected all interior components. Checked landing gear condition as well as wheels and brakes. C/W FAR 91-207D for ELT inspection. Next battery change due by December 2022

I certify that this Airframe engine has been inspected on August 14, 2017 in accordance with the manufacturers maintenance and inspection procedures and was found to be in a condition for safe operation

A&P [REDACTED] [REDACTED]

OT IM EF

Photo 2 – Last Condition Inspection - Airplane