



RECORD of CONVERSATION

Millicent Hill
Air Safety Investigator
Eastern Region Aviation

Date: June 16, 2020

NTSB Accident Number: ERA18LA210 – Lakewood, NJ

- Following the accident this investigator spoke with the pilot by telephone and requested a NTSB Form 6120.1 be filled out and submitted.
- The pilot provided a statement to the FAA, which was received by the NTSB on August 28, 2018.
- Another request for the form was made via telephone and email on April 17, 2019.
- As of this writing the NTSB Form 6120.1 was never received by the NTSB IIC.