



## **MEMORANDUM FOR RECORD**

**Aaron McCarter**  
**Air Safety Investigator**  
**Eastern Region Aviation**

---

**Date: July 29, 2020**  
**Person Contacted: Owner/Instructor (Dave Gallagher)**  
**NTSB Accident Number: ERA18LA257**

---

### **BRIEF**

Sent a clarifying email to the instructor asking him to elaborate on the sound and power of the engine during the accident flight. He responded by saying that the engine and aircraft were in a normal condition during the accident flight and that no mechanical irregularity was discovered during post-accident maintenance. In addition, after the airplane was repaired, he flew with the accident pilot again and recreated the “scenario” to show him the effects of performance.

[END]