



Photo 1 –View of Gyroplane at rest (Courtesy of FAA)



Photo 2 – View of Main Rotor and Tail Section Damage (Courtesy of FAA)




Photo 3 – View of underside of gyroplane (Courtesy of FAA)