

10/04/18 N198LT CAVALON \$V00299 HM 16.6

Complied with Conditional annual inspection IAW Autogyro cavalon MM. Oil line on bottom of engine needs safety wire, resafetied. Left jam nut on rudder cable loose need tightening, retightened. Head shift required and complied with. Aircraft found safe for flight.



Matthew Hood

10/04/18 N198LT CAVALON ROTAX 914UL \$9.576.060 HM 16.6

Complied with Conditional annual inspection. Oil line of bottom of engine needs safety wire, resafetied. Engine found safe for flight.



Matthew Hood

FLIGHT LINE AVIONICS, INC.
SUPPLEMENTAL LOG BOOK ENTRY

Aircraft Registration # N198LT S/N: V00299 Model: AutoGyro Cavalon

.....
Performed transponder test and the following listed are found to comply with requirements of FAR 91.413 IAW Appendix F of Part 43.

Transponder Model: TRT800H S/N: 30918416 Cal. Date: 10/5/2018

Details on file at this Repair Station under Work Order: # 12207

Signed: _____ **DUE NEXT: 10/2020**

North County Airport