



Memorandum For Record

Timothy W. Monville
Sr. Air Safety Investigator
Eastern Region

Date: August 12, 2020
NTSB Accident Number: ERA19FA060

As part of the investigation, NTSB asked personnel of Fort Lauderdale Executive Airport (FXE) to capture any security video that captured engine runs being performed. A video clip titled "12_1_2018 9_21_26am" lasting 36 minutes 37 seconds was provided.

A review of the video revealed that at 0921:28, the airplane came into view taxiing. The right side of the airplane was in prominent view. The airplane remained in view until 0921:56 while taxiing then went out of view. The airplane came back into view at 0922:42, taxiing in the opposite direction, then turned slightly to the left facing the camera and stopped about 0923:06. The airplane remained on that spot until 0957:29, at which time the airplane began taxiing. Between 0923 and 0957, with a view of the airplane nearly head-on, an occupant was noted outside the airplane near the left and right engines. It could not be determined by the video who was outside the airplane or what portion of the engines were being worked on.