

From: [REDACTED]
To: [REDACTED]
Subject: N26617 Aspen Evolution 2500 series installation and configurations
Date: Friday, March 08, 2019 11:51:28 AM

I, Christopher Thomas Loeffel, Avionic Technician apprentice with Boggs Avionics, Installed Aspen Evolution 1000PFD, Aspen Evolution 1000MFD, and Aspen Evolution 500MFD, work order 2012 on file with Boggs Avionics at Seahawk Aviation [REDACTED] Wilmington, NC. 28405. The installation was performed during the months of April and May 2018 under the direct supervision of George Boggs CRS# YOGR280Y. During this installation ADS-B functions were not used in any of the Aspen Evolution RS-232 ports on any of the units. As per configuration, and check out procedure, the verification is located on pages 242 and 243 under RS-232 configuration A-B documents submitted. Aspen EFD1000 mandatory service bulletin 2018-01 is not applicable due to RS-232 ADS-B functions not in use during the installation process, and check out procedure when aircraft was returned to service after Avionic installation.

Christopher Loeffel
Seahawk Aviation