



NATIONAL TRANSPORTATION SAFETY BOARD

Eastern Region – Ashburn, Virginia

Record of Conversation

Who: JJ Anglin, Anglin Aircraft Recovery

RE: ERA19LA024, N8319D

In a telephone conversation, Ms. Anglin stated that when they recovered the airplane, no fuel was found or drained from the right main tank and about 4.5 gallons were drained from the right auxiliary tank. About 10 gallons were recovered from the left main tank and about 1 gallon was drained from the left auxiliary tank.

Leah D. Read, Sr. ASI