



Photo 1 – View of top of inboard right wing showing buckling damage




Photo 2 – View of airplane on taxiway with right gear collapsed