



MEMORANDUM FOR RECORD

Douglass Brazy
Air Safety Investigator
Eastern Region Aviation

March 22, 2019

Subject: N519P, Bell OH-58A, 03/13/19, Ponte Vedra Beach, Florida, NTSB Investigation ERA19LA126. Record of Conversation with Federal Aviation Administration Inspector Robert Haynes of the Orlando, Florida Flight Standards District Office

On March 22, 2019, Mr. Haynes provided the following information via telephone:

The helicopter sustained substantial bending/buckling damage to the tail boom, and damage to the fuselage frame around the windscreen and doors. Fuel was present in the fuel tank, and a sample of fuel taken from the fuel tank was clear in color with no water present. No fuel or other fluid leaks were observed.

<end>