

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
2017				
Sept 10	TTIS		4352.7	Assembled Accessory gear box and installed cylinders on engine. All
	TSMOH		2352.7	connecting rod bearings .020 oversize,
	TSTOH		0	pistons .30 oversize as well as rings
				oil seal and compression are .020 oversize
				Engine installed on Super Acro Sport I
				N20FB. Engine run and leak check
				No defects noted. Engine run IAW
				Lycoming overhaul manual. Engine
				is returned to service. [REDACTED]
				[REDACTED] ATP
April 10	TTIS		4362.7	Ground run engine to check systems.
2019	TSMOH		2362.7	Completed compression check #1 76/80
	TSTOH		10.0	#2 76/80 #3 75/80 #4 76/80. Cleaned
				and checked gap on spark plugs, verified
				Timing. No leaks found. Oil change
				due within next 15 hours of break
				in. Engine Return to service [REDACTED]

DATE 2018 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
April 19			258	Aircraft run and taxi all flights controls checked good aircraft + taxi of aircraft good solid controls throughout all phases of ground run. [REDACTED]
4-20-2018				[REDACTED] ATP I certify that this aircraft has been inspected in accordance with scope and detail FAR 43 appendix D and been found in a condition for safe flight [REDACTED] [REDACTED] IA