




Photo 1 – GPS Track Cruise Flight and Descent Profile




Photo 2 – View of Airplane as Found (U.S. Park Service)

LH Magneto

- No masking tape marking
- No writing on capacitor
- Gasket still attached
- Note position of damaged pieces in close up picture
- Note broken gear teeth away from red dot



Photo 3 – View of Left Magneto During Disassembly (Myers Aviation)



Identifying marks of the RH magneto

- Bold clear red stripe on gear
- White writing on capacitor
- Two broken gear teeth on top side
- Masking tape

Photo 4 – View of Right Magneto During Disassembly (Myers Aviation)