



NTSB MEMORANDUM FOR RECORD

Lynn Spencer
Aviation Investigator
Eastern Region, Office of Aviation Safety (ERA)
National Transportation Safety Board

Subject Matter: Camshaft Gear on Continental engine S/N 691404
NTSB Accident Number: ERA19LA264

In an email with Continental Engines, I was informed that engine S/N 691404 was assembled in 2007 and would have had the new, wider camshaft gear, and at that time, Continental would no longer have had any of the old gears in stock.