

ENGINE SERVICE AND

DATE	TIME RUN		TIME SINCE OVERHAUL		INSTALLATIONS, INSPECTIONS, NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE
	HRS.	MIN.	HRS.	MIN.	
BROUGHT FORWARD →					
Oct 30	20		1794	4	
Nov 3	24		1798	6	
14	30		1801	6	
16	30		1804	6	
28	18		1806	4	
12-23-98	1819	2			THIS ENGINE WAS REMOVED FROM ROTORCRAFT WORK ORDER # 19074 AT ROBINSON YV3R012M, 2901 AIRPORT DRIVE



ROBINSON HELICOPTER CO.

**2901 AIRPORT DRIVE
TORRANCE, CA 90505**



This engine has been overhauled in accordance with the applicable manufacturer's Overhaul Manual and other FAA-approved procedures. Applicable Federal Aviation Administration Airworthiness Directives have been complied with. All parts have been inspected and have been determined airworthy to return to service. Accessories are either new or newly overhauled.

Engine Model: O-540-F1B5
 Serial Number: L-24817-40A
 Date: 10 March 1999
 Total Time: 1824.2 Hours
 Work Order: 19267

Authorized Signature

[Signature]
 Robinson Helicopter Company
 FAA-Certificated Repair Station
 YV3R012M

TOTAL THIS PAGE	
TOTAL FROM PREVIOUS SUMMARY	
TOTAL SINCE MFG.	1824.2

CARRIED FORWARD