



Areas of buckling noted

Photo 1 – Left Side of Fuselage, Areas of Buckling Noted (Photo Courtesy of FAA)



Photo 2 - Buckling Noted on Rear Left Side of Fuselage (Photo Courtesy of FAA)



Photo 3 – View of Airplane Tire Tracks and Runway 34 (Photo Courtesy of FAA)



Photo 4 – View of Tire Tracks and Runway 34 Threshold (Photo Courtesy of FAA)