

Inbound to Runway 22 at 0605
3/8 Rt & 1 gallon Left tank
Tank Switched to left
for landing. Engine began
to run poorly. Switched
Back to right tank.
Started back up & quit
3 times. Impacted trees
and came to rest inside
Airport perimeter fence.

 6/8/2020
11