



MEMORANDUM OF CONVERSATION

Aaron McCarter
Air Safety Investigator
Eastern Region Aviation

Date: 07-27-2020
Person Contacted: Pilot/Owner; Larry Morton
NTSB Accident Number: ERA20CA257

Narrative:

Phone call with the pilot/owner to discuss the events surrounding the airplane accident.

The pilot stated he simply failed to reposition the landing gear prior to landing. The “airplane was fine, he messed up.” He confirmed there were no pre accident failures or malfunctions that led to the accident.

[END]