

Screenshots from Surveillance Cameras

Final seconds of accident flight

NTSB Accident Investigation: ERA20FA020, N959MJ


Camera #1
Screenshot 1

Near, New Dover
Road, Colonia, NJ



Camera #1
Screenshot 2

Near, New Dover
Road, Colonia, NJ



Camera #1
Screenshot 3

Near, New Dover
Road, Colonia, NJ



Camera #1
Screenshot 4

Near, New Dover
Road, Colonia, NJ



Camera #2
Screenshot 1

Near, Montrose
Ave., Colonia, NJ



Camera #2
Screenshot 2

Near, Montrose
Ave., Colonia, NJ



Camera #2
Screenshot 3

Near, Montrose
Ave., Colonia, NJ



Camera #2
Screenshot 4

Near, Montrose
Ave., Colonia, NJ

