

 DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION REPORT OF AIRCRAFT ACCIDENT (Continuation Sheet)	REPORT DATE December 02, 2019	REPORT NO. 19-001-OCF-FCT
	NAME OF REPORTING FACILITY Ocala Airport FCT (OCF)	

14. CHRONOLOGICAL SUMMARY OF FLIGHT
 October 31, 2019

ALL TIMES BELOW ARE COORDINATED UNIVERSAL TIME
 UNLESS OTHERWISE SPECIFIED

1524 N959CM contacted Ground Control (GC) and requested taxi instructions for a maintenance test flight to the west.

1525 GC instructed N959CM to taxi to Runway 18. N959CM acknowledged but turned on the taxiway heading for Runway 26. GC informed N959CM of the correct taxiway for Runway 18. N959CM acknowledged.

1528 N959CM called Local Control (LC) for departure.

1529 LC cleared N959CM for takeoff and issued instructions to fly runway heading for C172 traffic on right downwind. N959CM acknowledged.

1530 LC cleared N959CM to proceed on course. N959CM acknowledged.

1531 LC requested N959CM to advise direction of flight. N959CM responded headed to the west. LC advised N959CM appeared to be headed east and instructed N959CM to turn west and proceed on course. N959CM acknowledged.

1532 LC observed N959CM in a left turn and requested N959CM to advise intentions. N959CM reported the need to return to the airport. LC instructed N959CM to enter left downwind for Runway 18. LC observed N959CM disappear below the tree line and smoke.

1533 LC attempted to contact Air One a Sheriff Department helicopter. Air One did not respond. GC notified airport emergency personnel.

No More Follows