

Gretz Robert

From: Daniel Veillette [REDACTED]
Sent: Monday, August 24, 2020 1:55 PM
To: Ouellet, Jérôme
Cc: Gretz Robert
Subject: Re: Accident Mustang II

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Hi a little correction .. !! the speed was in MPH .. !! thank you so much
Daniel
Envoyé de mon iPhone

Le 24 août 2020 à 1:31 p.m., Ouellet, Jérôme <Jerome.Ouellet@bst-tsb.gc.ca> a écrit :

M. Gretz

Just got off the phone with M. Veillette and the speed you are asking about is 270-275kts. (above VNE of 220-230kts)

Regards

Jérôme Ouellet

Enquêteur / Agent des Opérations / Opérations internationales et enquêtes majeures - Air
Bureau de la sécurité des transports du Canada / Gouvernement du Canada
[REDACTED]

Investigator / Operations Officer / International Operations and Major Investigations - Air
Transportation Safety Board of Canada / Government of Canada
[REDACTED]

<image001.png>

From: Gretz Robert [REDACTED]
Sent: Monday, August 3, 2020 7:42 AM
To: 'Daniel Veillette' [REDACTED]
Cc: Ouellet, Jérôme [REDACTED]
Subject: RE: Accident Mustang II

Hi Mr. Veillette,

I hope you had a good weekend. I had one follow-up question. You mentioned that during the first flight with the new owner, he flew at airspeeds above VNE. Do you remember about what maximum airspeed he obtained?