



Millicent Hill
ERA20FA118
Eastern Region

Date: 04/13/2020
Subject: Autopsy Report Summary

An autopsy of the pilot was performed by Department of Forensic Sciences, Georgia Bureau of Investigation. The autopsy report was reviewed by the NTSB Investigator-In-Charge. According to the autopsy report, the cause of death was blunt force injuries, and the manner of death was accident.