

NTSB Review of Illustrated Parts Catalog and Photographs

ERA20LA008

N86MN





Photo 1 – View of the nose landing gear actuator (Photograph Courtesy of FAA)




Photo 2 – View of the nose landing gear actuator attachment area (Photograph Courtesy of FAA)

Raytheon Hawker 800/ 850XP illustrated parts catalog, Item 130,
Part Number 25UN597. Photographs courtesy of Delta Private Jets.



Raytheon Hawker 800/ 850XP illustrated parts catalog, Item 95, Part Number AIR45404.
Photographs courtesy of Delta Private Jets.



Raytheon Hawker 800/ 850XP illustrated parts catalog, Items 80 (pin-split), 85 (nut), 90 (washer). Photo of *exemplar* missing parts. Photographs courtesy of Delta Private Jets.





Photo 3 – View of the accident airplane on the runway (Photograph Courtesy of FAA)



Photo 3 – View of the substantially damaged fuselage (Photograph Courtesy of Delta Private Jets)