



MEMORANDUM for RECORD

Millicent Hill
Air Safety Investigator
Eastern Region Aviation

Date: December 17, 2019
Person Contacted: George Long
NTSB Accident Number: ERA20LA052 – Grove City, PA

This investigator interviewed Mr. Long by telephone and email. He reported the following:

- The pilot stated he was out flying around “burning up some gas.”
- He had departed Grove City Airport (29D) about 1100 and flew around for about 30 to 45 minutes.
- While on final for runway 28, about 200 ft, he noticed the PAPI lights indicated he was low. He stated there was one red and one white light. He attempted to add power but the left engine did not respond. He attempted to restart the engine to no avail.
- He stated there were multiple airplanes on the ramp and he did not want to hit them, he pulled power to the right engine and landed in the grass to the left of the runway.
- He had owned the airplane for about one year.