

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Research and Engineering
Materials Laboratory Division
Washington, D.C. 20594



February 2, 2021

MATERIALS LABORATORY ERRATA REPORT

Report No. 20-047B

1. ACCIDENT INFORMATION

Place : Fletcher, North Carolina
Date : December 28, 2019
Vehicle : Piper PA-32RT-300, N27GB
NTSB No. : ERA20LA062
Investigator : Todd Gunther, AS-ERA

2. COMPONENTS EXAMINED

Remnants of an oil pump case and impellers
Remnants of an oil pump drive gear

3. DETAILS OF THE EXAMINATION

This report corrects errors identified in Materials Laboratory Factual Report 20-047, produced on January 12, 2021. The corrections are as follows:

- Page 2, Paragraph 6, Line 4 – The markings should state, “51B23274 V6498 48/12”.

Erik M Mueller
Materials Research Engineer