



Photo 1 – Digital Photograph From ARFF Deputy Chief MYR Airport. Left Forward View of the Airplane Where it Came to Rest.



Photo 2 - Digital Photograph From ARFF Deputy Chief MYR Airport. Right Side View of the Airplane Where it Came to Rest.



Photo 3 - Digital Photograph From ARFF Deputy Chief MYR Airport. View of the Left Side of the Instrument Panel. Note the Roll Indicator.




Photo 4 - Digital Photograph From Atlanta Air Salvage. View of the Position of the Pitch Trim Actuator which was near Full Airplane Nose Down.