



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety

May 29, 2020

ENGINE EXAMINATION

ERA20LA164

(2 Pages)

1.0 EXAMINATION PARTICIPANTS:

Lynn Spencer
Air Safety Investigator
National Transportation Safety Board
Ashburn, VA

JD Corrow
Recovery Specialist
Atlanta Air Salvage
Griffin, GA

Dave Bentoski
A & P Mechanic
Atlanta Air Salvage
Griffin, GA

2.0 SUMMARY

The follow-up examination of the engine of N772SG was conducted on May 29, 2020, at Atlanta Air Salvage, Griffin, Georgia, under the video supervision of the NTSB due to the Covid pandemic. The engine was test run.

3.0 DETAILS OF THE EXAMINATION

No exterior damage noted to engine other than debris in exhaust pipe ends and slight firewall damage. To facilitate the examination, the airplane was secured to a trailer, the propeller was removed, and a test propeller was installed. The main fuel line was disconnected and connected to a fuel supply to test run the engine.

The engine was started twice with no anomalies noted. The engine was allowed to idle for one minute, and all engine indications appeared normal. A higher RPM run-up was not performed for safety reasons.

Submitted by: Lynn Spencer