



MEMORANDUM FOR RECORD

Investigator: Brian C. Rayner
Senior Air Safety Investigator
NTSB - Eastern Region

Date: June 4, 2020
Subject: Matthew Geer – NTSB Form 6120.1
NTSB Accident Number: ERA20CA188 Clarksville, TN

Narrative:

The pilot did not submit an NTSB Form 6120.1. as the necessary information was immediately presented at the time of the accident and the follow-up examination of the airplane.

The information was gathered from FAA Aviation Safety Inspector David Alderman, who responded to the scene, documented the wreckage, interviewed witnesses, recovered aircraft and pilot records, and provided FAA records.