



NATIONAL TRANSPORTATION SAFETY BOARD

Eastern Region – Ashburn, Virginia

Summary Email Report – NTSB Recorder Lab

Email Report:

The Vehicle Recorder Division received a Sandel SN3500 electronic horizontal situation indicator (EHSI), P/N 90165. The device arrived exhibiting signs of severe fire damage (ERA20LA206_01.jpg). The non-volatile memory chips were located, however, they also exhibited signs of severe thermal damage (ERA20LA206_02.jpg). Due to the damage, no data could be recovered from the device.

Prepared by: Kyle Garner, Recorder Specialist, NTSB RE-40



(ERA20LA206_01.jpg)



(ERA20LA206_02.jpg)