

Twin Commander

Model 500S Aircraft Fuel System equipped with the EA515B-1404M Fuel Sending Unit and the 850089 Fuel Gage.

It is Twin Commander's understanding that if the variable contact wire of the EA515B-1404M Fuel Sending Unit becomes severed and is considered electrically to be an open circuit that the 850089 Fuel Gage can read at the extreme ends of the 850089-Fuel Gage or respond erratically. It is Twin Commander's recommendation to follow the prescribed Aircraft Maintenance Manual, Section V Fuel System Fuel Quantity Indicating System, and Inspection Interval per Section 2 Ground Handling Servicing and Airframe Maintenance for the Twin Commander 500s Aircraft, or any time the Fuel System quantity accuracy comes into question.

07-11-2022

David Allison


Twin Commander