

NTSB Investigation: ERA20LA330

Figures from Report

Dead tree with vegetation growth




Photo Courtesy FAA

NTSB Accident: ERA20LA330

Spraying equipment located in the field, about 25 ft east of the dead tree



Photo Courtesy FAA



Preaccident photograph of spraying equipment (Source: AOPA)

Figure 1: View of the dead tree in the field being sprayed, with accompanied photographs of the agriculture spraying equipment located in the field.




Figure 2: Overview of the accident site area