



Daniel Boggs
Air Safety Investigator
Eastern Region Aviation

Date: July 6, 2021
NTSB Accident Number: ERA21FA130

Medical and Pathological Information:

According to the Officer of the Medical Examiner, Virgin Islands Department of Justice autopsy report, the cause of the pilot's death was multiple injuries due to blunt force trauma.

Toxicology testing performed by the FAA's Forensic Services Laboratory on the pilot's blood and urine identified no evidence of impairing drugs or alcohol.