



Photo 1 – View of the main wreckage from the direction of travel.



Photo 2 – View of the main wreckage looking back at the direction of travel.



Photo 3 – Fuel selector valve.

Piper | eBay

8 TURBO LANCE PA32RT300: 5665 TT, 1494 SMOH (1800 TBO) NEXT ANNUAL DUE 22 JAN 2022,

COMPRESSION : 1. 74/80, 2. 68/80, 3. 69/80 4. 72/80 5. 79/80 6. 76/80. (5 & 6 are new). 200 hrs on turbo charger
PROP OVERHAULED 22 JUN 2018 SOUTH COAST PROPELLER SERVICE

AVIONICS: 1, (AUDIO PANEL GMA 340) , 2. (COM 1 GTN 430W(, 3. (COM 2 GARMIN SL30). 4. (ADS-B GDL82) 5, (COLLINS ADF)
6. (FM STEREO AND TAPE DECK WITH IPAD STEREO) 7. (TRANSPONDER GARMIN 327) 8. KLM89 B IFR CERTIFIED GPS.
9. (MITCHEL BACKUP ELECTRIC DG) 10. (AUTOPILOT IIIC COUPLES TO BOTH GLIDE SLOPES). 11.(EDM-700 ENGINE ANALYZER.) 1
STORMSCOPE)

ISVI INSTANT VERTICAL SPEED INDICATOR

ELECTRIC AILERON TRIM.

FACTORY OXYGEN SYSEM. 6 NEW FACE PACKS ..CANNULA. PAINT. 8/10 INTERIOR 7.5/10

NO DAMAGE HISTORY (EXCEPT....ONE DEER ON LEFT WING)

CLUB SEATING WITH ICE CHEST

NEW TIRES BRAKES

NO CORROSION / DIGITAL CLOCK AND OAT GAUGE

FRONT SEATS NEW BLUE VELOUR

LOG BOOKS COMPLETE SINCE FACTORY NEW...HISTORY AS CORPORATE AIRCRAFT AND OWNED BY CFI FOR LAST 5 YEARS. W
5 HRS OF COMPLIMENTARY INSTRUCTION TO PURCHASER .

SERIOUS CROSS COUNTRY MACHINE

02/21/2021 11:23

Photo 4 – Sales advertisement for the airplane.



Photo 5 – Google map view of the wreckage and the airport.