



Millicent Hill
ERA21FA133
Eastern Region

Date: 6/10/2021
Subject: Autopsy Report Summary

An autopsy of the pilot was performed by Alabama Department of Forensic Sciences. The autopsy report was reviewed by the NTSB Investigator-In-Charge. According to the autopsy report, the cause of death was multiple blunt forces, and the manner of death was accident.