

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations
DATE				Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

N24RG Tach; 1724.3 TT; 1724.3

AIRFRAME

C/W FAR91.207(d) ELT inspection ELT battery replacement due 10/2021
 C/W AD2011-10-09 seat and seat track inspection per inspection per
 Para (g)(1-10). Install a new BA-5705 engine air filter.
 Remove shimmy dampener and install new o-rings, service with 5060
 hydraulic fluid, and reinstall.
 Install a new carb heat hose from #3 stack to carb heat.
 Install a new B3-5-1 band filter.
 Install new brake linings on left brake P.N 066-10500.
 Remove right brake caliper and install a new MS28775-224 o-ring. Bleed brake
 with 5606 hydraulic fluid.
 Lubricate all flight controls, hinges, and rod ends.

**I certify that this aircraft has been inspected I/A/W an annual type
 inspection and was found to be in airworthy condition. AD summary
 checked thru 2020-19**

The aircraft and/or component identified above was repaired and
 inspected in accordance with current regulations of the Federal
 Aviation Administration and is approved for return to service.
 Pertinent details of the repair are on file at this station under
Service Order No. 63099, Dated: 9/16/2020

FAA Approved Repair Station No. B2ER144J
 Boshart Enterprises and Aircraft Services, Inc.
 Genesee County Airport Batavia, N.Y. 14020

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------------	---------------------------	-------------------	-----------------------------	---

N24RG Tach; 1724.3 TT; 1724.3 SMOH; 673.5 ENGINE

Drain engine oil, remove and inspect oil filter. Install a new CFO100 oil filter and service with 7 qts of Aeroshell 15W50.

Install a new BA-5705 engine air filter.

Install all new 69603 intake hoses and 71973 gaskets on all cylinders.

Compress Test: 1)78 2)78 3)74 4)74

I certify that this engine has been inspected I/A/W an annual type inspection and was found to be in airworthy condition. AD summary checked thru 2020-19

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under

Service Order No. 63099 / dated: 9/16/2020

FAA Approved Repair Station No. B2ER144J
Boshart Enterprises and Aircraft Services, Inc.
Genesee County Airport Batavia, N.Y. 14020

☐ **HUB & BL** **N24RG**

Date **Tach; 1698.6**
Dress propeller blades and inspect complete propeller assembly for defects.

19 _____ **I certify that this aircraft has been inspected I/A/W an annual type inspection and was found to be in airworthy condition. AD summary checked thru 19-18**
Next Inspection Due:

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station.

Date **N24RG Tach; 1724.3 SMOH; 971.1**
19 _____ **PROPELLER**
Service Order No. 62775 Dated: 9/25/19

Next Inspection Due: [Redacted]
FAA Approved Repair Station No. B2ER144J
Boshart Enterprises and Aircraft Services, Inc.
Genesee County Airport Batavia, N.Y. 14020

Date **I certify that this propeller has been inspected I/A/W an annual type inspection and was found to be in airworthy condition. AD summary checked thru 2020-19**
19 _____

Next Inspection Due: [Redacted]
The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under **Service Order No. 63099 Dated: 9/16/2020**

Date **PROPELLER**
19 _____
Next Inspection Due: [Redacted]
FAA Approved Repair Station No. B2ER144J
Boshart Enterprises and Aircraft Services, Inc.
Genesee County Airport Batavia, N.Y. 14020

Mech. Cert. # or Repair Station

Date

19 _____

Next Inspection Due:

Date

19 _____

Next Inspection Due:

Date

19 _____

Next Inspection Due: