



Daniel Boggs
Air Safety Investigator
Eastern Region Aviation

Date: June 8, 2021
NTSB Accident Number: ERA21FA194

Medical and Pathological Information:

An autopsy of the right seat pilot was performed by the Office of the Chief Medical Examiner, Jacksonville, Florida. The pilot's cause of death was Cutaneous thermal injuries, inhalation of products of combustion, and blunt traumatic injuries.

An autopsy of the left seat pilot was performed by the Office of the Chief Medical Examiner, Jacksonville, Florida. The pilot's cause of death was atlantoaxial dislocation due to blunt impact to head.

Toxicology testing performed by the FAA's Forensic Services Laboratory on the left seat pilot's blood and urine detected amlodipine which is a high blood pressure medication and is not generally considered impairing.