



MEMORANDUM for RECORD

Ralph E. Hicks
Senior Air Safety Investigator
Eastern Region Aviation

Date: July 27, 2021
Autopsy Findings
NTSB Accident Number: ERA21FA258 – Yulee, Florida

According to the Office of the Medical Examiner, Jacksonville, Florida autopsy reports, the cause of death of the flight instructor was multiple blunt traumatic injuries and the manner of death was accident. The cause of death of the student pilot was multiple blunt traumatic injuries and the manner of death was accident.