



MEMORANDUM FOR RECORD

Timothy W. Monville
Sr. Air Safety Investigator
Eastern Region

Date: January 19, 2022
NTSB Accident Number: ERA21FA346

Medical and Pathological Information:

An autopsy of the co-pilot was performed by the Office of the Chief Medical Examiner, Farmington, Connecticut. The cause of death was blunt injuries of head, neck, torso, and extremities.