

Shearer Aviation Services, Inc.
LOG ID# 6382 06-June-2022
N720RP S/N 32-8006027 PIPER PA32-301 TACH 4454.6

Pg 1 / 1

N720RP

INSTALLED NEW NOSE TIRE 5.00-6/6 PLY S/N 1337T00172 AND TUBE. END.

JEFFREY W SCHWANGER

Shearer Aviation Services, Inc.
LOG ID# 6458 11-August-2022 HOBBS 1634.8
N720RP S/N 32-8006027 PIPER PA32-301 TACH 4509.9

Pg 1 / 1

N720RP AIRFRAME

CLEANED AND INSPECTED FUEL SUMP SCREEN. CLEANED AND REPACKED MAIN AND NOSE WHEEL BEARINGS. SERVICED TIRE PRESSURES. SERVICED BATTERY. C/W YEARLY ELT INSPECTION IAW FAR 91.207 D. ELT BATTERY DATE JUNE 2028. GREASED MAIN LANDING GEAR. SERVICED BRAKE RESERVOIR. LUBRICATED FLIGHT CONTROLS. CONDUCTED LIGHT CHECK. INSTALLED NEW RIGHT STEERING BUNGEE BOOT. CLEANED BELLY. REPLACED LEFT FUEL CAP GASKET. REPLACED ALL SCREWS AND HARDWARE AT BOTH STALL WARNINGS. REPAIRED LEFT STABILATOR TIP ON LEADING AND TRAILING EDGES. REPLACED AFT ROD ENDS ON LEFT AND RIGHT AILERON ACTUATORS. REPLACED ELT WITH ARTEX ELT 345, OPS CHECKED NORMAL. REPLACED LEFT MAIN TIRE P/N 172-317-0 S/N 2054T00065. REMOVED, CLEANED AND RESEALED LEFT BRAKE CALIPER. FLIPPED RIGHT MAIN TIRE ON WHEEL ASSEMBLY. REPLACED LEFT FLAP GROUND STRAP HARDWARE. CLEANED GROUND STRAP. REPLACED LEFT AILERON GROUND STRAP HARDWARE. CLEANED GROUND STRAP. REPLACED LEFT BRAKE DISC. REPLACED RIGHT BRAKE DISC. TIGHTENED LEFT LOWER OUTBOARD GEAR LEG ATTACH MOUNT BOLT. RELINED AND CONDITIONED LEFT AND RIGHT BRAKE LININGS. REPLACED ALL BRAKE HOSES. REPAIRED RIGHT FORWARD LOWER COWL AT COWLING RECEPTICAL. BLED BRAKES. SECURED VACUUM HOSE THAT WAS CATCHING CONTROL YOKE CHAIN. REPLACED CO-PILOT'S LEFT BRAKE CROSSOVER HOSE FITTING. C/W AD 76-07-12 BY OPS CHECK, NO DEFECT NOTED, NEXT DUE TACH 4609.9. C/W AD 2015-19-07 BY INSPECTION, NO DEFECT NOTED. END.

I CERTIFY THAT THIS AIRCRAFT WAS INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. END.

JEFFREY W SCHWANGER

Shearer Aviation Services, Inc.
LOG ID# 6485 11-August-2022
N720RP S/N 32-8006027 PIPER PA32-301

Pg 1 / 1

N720RP AIRFRAME

REMOVED AMERI-KING AK450 ELT S/N459572 AND INSTALLED ARTEX 345, P/N A3-06-2880 S/N 391808-037, IN SAME POSITION AS FORMER ELT.

JEFFREY W SCHWANGER

SUB-TOTAL this page

TOTAL—Carry forward to next page

Make Piper Model PA32 S.N.
P.N. 65342-002 Title Rudder assy.

Pg 1 / 1

This aircraft/component/subassembly identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this agency under Work Order No. 22029

Date: April 20, 2021 Signed:

Airframe Components
by Williams, Inc.
9838 N 1100 E
Kendallville, IN 46755



WWFR 300K

Pg 1 / 1

REMOVED AND REPLACED RUDDER WITH OVERHAULED RUDDER.END.

Kevin Wenrich

Shearer Aviation Services, Inc.
LOG ID# 6008 30-July-2021
N720RP S/N 32-8006027 PIPER PA32-301

Pg 1 / 1

N720RP AIRFRAME
JULY 30, 2021 TACH 4273.6 TOTAL TIME 3673.7

CLEANED AND INSPECTED FUEL SUMP SCREEN. INSPECTED VACUUM REGULATOR FILTER. CLEANED AND REPACKED WHEEL BEARINGS. SERVICED MAIN TIRE PRESSURES. SERVICED BATTERY. C/W YEARLY ELT INSPECTION IAW FAR 91.207D. ELT BATTERY REPLACEMENT DUE DATE IS DECEMBER 2025. GREASED GEAR. SERVICED HYDRAULIC BRAKE RESERVOIR. LUBED FLIGHT CONTROLS. CHECKED LIGHTS. PRESSURE CHECKED FUEL SYSTEM FOR LEAKS. RESEALED NOSE STRUT. INSTALLED HEAT SHIELD ON LOWER COWL UNDER MUFFLER AREA. TIGHTENED SECOND FROM OUTBOARD UPPER LEFT GEAR LEG ATTACH BOLT. RELINED LEFT BRAKES. REPLACED LEFT BRAKE PRESSURE PLATE. CLEANED AND TREATED CORROSION AS NEEDED ON BELLY AT RIGHT FORWARD STRACK AREA. REPLACED NUT PLATE ON LEFT WHEEL NUT. CLEANED GROUND ON TAIL NAV LIGHT. CLEANED BELLY. C/W AD 2013-02-13 BY INSPECTION. NO DEFECTS NOTED. C/W AD 76-07-12. NO DEFECTS NOTED.END

JULY 30,2021 TACH 4273.6 TOTAL TIME 3673.7

I CERTIFY THAT THIS AIRCRAFT WAS INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.END

JEFFREY W SCHWANGER

Shearer Aviation Services, Inc.
LOG ID# 6305 11-April-2022
N720RP S/N 32-8006027 PIPER PA32-301

Pg 1 / 1

N720RP AIRFRAME
APRIL 8,2022 TACH 4426.2

INSTALLED NEW ELBOW AND AERODUCT ON INDUCTION AIR FILTER TO FUEL SERVO. END

JEFFREY W SCHWANGER

SUB-TOTAL this page

TOTAL—Carry forward to next page