



RECORD OF CONVERSATION

Robert Gretz
Senior Air Safety Investigator
Eastern Region Aviation

Date: November 16, 2020
Person Contacted: Cecil Brewer, Huddleton, VA
NTSB Accident Number: ERA21LA022

Narrative:

Mr. Brewer was interviewed via telephone. Mr. Brewer is an A&P/IA. He examined the fuel selector handle today. He stated that when the handle was actuated by hand, the fuel valve operated normally and there was no looseness.