



MEMORANDUM FOR RECORD

Maintenance Facility Statement

Lynn Spencer
Air Safety Investigator
Eastern Region Aviation

Date: March 8, 2021; 1330 EST
Person Contacted: Byron Maynard (Lincoln Skyways, President)
Contact # [REDACTED]
NTSB Accident Number: ERA21NA108

Narrative:

The following is a summary of a conversation that occurred with the individual named above:

Mr. Maynard stated that on January 18, 2021, Mr. Mallo called Lincoln Skyways for assistance with checking the pressure on his airplane tires. He stated that one of airplane's hubcaps was "clocked wrong" and Mr. Mallo could not access the valve stem in order to check the tire pressure. He stated that mechanic Ken Dzor went to assist Mr. Mallo. Mr. Dzor fixed that one hubcap and checked air in all three tires. Mr. Mallo provided the appropriate tire inflation values from the POH, and Mr. Dzor added air to the two main landing gear tires as well as the nosewheel landing gear tire.