

Date	Hour Meter Time	T. Time in service	Description of work performed
6/15/2020	163	437.7	* Replace Geabox oil with recommended oil * Replaced sparkplugs Gapped to specs * Replaced Rims and Tires - added hydraulic brakes (BlackMax BX1000) * Added Copper fuel Pickups and replaced fuel Lines * Installed VHF comm Radio (MGL V6) with ELT antenna * Installed new Rotax 503DCDI * Installed new Lord Engine Mounts * Rebuilt Fuel Pump * Installed LifePO4 6 A/H battery to power efis and radio * Sent IVO propelor to IVO to refurbish and Zero time it - Reinstalled to Specs * Installed new full length Wind Shield - 1/8" Poly Carbonate * Installed fuel shutoff valve and new primer bulb - relocated the manual primer * Replaced the carpet * Installed new 4 point safety harness - <u>this may have save my life</u>
I certify that this aircraft has been inspected on 6/15/2020 in accordance with the scope and detail of appendix D to part 43, and was found to be in a condition for safe operation. Repairman Experimental Aircraft - Certificate # [REDACTED] Signed by _____			