

7150 Republic Airport, Room 216, East Farmingdale, NY 11735
Telephone: (631) 386-6108

REPUBLIC AIRPORT INCIDENT REPORT

Report #:	<u>202101001</u>	Reported By:	<u>ATCT</u>	Reported Via:	<u>Crash Phone</u>
Prepared By:	<u>Medina, Chris</u>	1 st Resp. Veh:	<u>R-1</u>	Souls Onboard:	<u>1</u>
Date:	<u>Jan. 10, 21</u>	Add'l Resp. Veh:	<u>R-3</u>	Wind:	<u>N13</u>
Day:	<u>Sunday</u>	A/C-Veh 1 ID:	<u>N421DP</u>	Visibility:	<u>10</u>
Location:	<u>2.25 Miles NW</u>	A/C-Veh 1 Type:	<u>C421</u>	Ceiling:	<u>CLR</u>
Alert Type:	<u>Alert 3</u>	Police:	<u>SCPD, NCPD</u>	NOTAM Issued:	<u>No</u>
Incident Type:	<u>Crash</u>	Mutual Aid:	<u>EFFD, PVFD</u>	Photos Taken:	<u>Yes</u>
Time Reported:	<u>1259</u>	Opr. License #:		FSDO Contacted:	<u>Yes</u>
Time of Incident:	<u>1301</u>	Opr's. Med. Date:	<u> </u>	Insp. Name:	<u>Daniels, Marvin</u>
Surface Condition:	<u>Dry</u>				

Primary Information

Name: Marc Capus
Address: [REDACTED]
Bellmore, NY 11710

Telephone: [REDACTED]

Additional Information (No)

Name: _____
Address: _____

Telephone: _____

Secondary Information (No)

Name: _____
Address: _____

Telephone: _____

Additional Information (No)

Name: _____
Address: _____

Telephone: _____

Insurance Information (No)

Name: _____

Policy #: _____

Telephone: _____

Address:

Detailed Description:

On 10 January 2021 at 1259L Republic Operations/Aircraft Fire Rescue received a call via crash phone by Air Traffic Control Tower that N421DP (Cessna 421B Golden Eagle) called inbound with an engine failure, ARFF Asst Chief Medina inquired if it was just one engine or both and was advised that both engines stopped. Operations Coordinator Perrien responded and stood-by in Rescue 3 and Operations Coordinator Basso responded in Rescue 1 at the airport. As Crash crews were on standby they could see the aircraft go inverted and then go down. Before N421DP lost both engines ATC was giving the pilot suggestions on where he could possibly land but the pilot stated that he was just going to put it down in a field. N421DP crashed 2.25 Miles Northwest of Republic Airport in Bethpage (150 Winding Road) at 1301L. Rescue 1 and 3 proceeded to the crash scene, meeting up with East Farmingdale, Plainview Fire Departments and Nassau County, State Police at 1315L. The pilot was pinned inside and was extricated by Nassau County ESU at 1334L and was transported to Nassau University Medical Center by Nassau County. Rescue 3 returned to base at 1410L. Inform (Lisa) was notified at 1354L. A protective foam blanket was applied by EFFD. FSDO investigators arrived at the scene 1515L (3:15PM) to conduct their investigation.

Responding agencies: FRG ARFF, Plainview FD, East Farmingdale FD, SCPD, NCPD, DEC.

Ops Coordinator Signature / Date: _____ 1/13/21 Ops Manager Signature / Date: _____

Report # 202101001