



MEMORANDUM FOR RECORD

Heidi Kemner
Senior Air Safety Investigator
Eastern Region Aviation

Date: 1/14/2021
NTSB Accident Number: ERA21LA101
Subject: Autopsy Report Summary

Medical and Pathological Information:

An autopsy of the pilot was performed by the Professional Pathology Services in Columbia, South Carolina. The autopsy report was reviewed by the NTSB Investigator-In-Charge. According to the autopsy report, the cause of death was blunt force injuries to head.