



MEMORANDUM FOR RECORD

Douglass Brazy
Air Safety Investigator
Eastern Region Aviation

June 15, 2021

Subject: NTSB investigation ERA21LA102, unregistered, Kolb Firestar KXP, Vineland, New Jersey, January 11, 2021. Autopsy and Medical Information – Pilot

Medical and Pathological Information:

According to the Office of Gloucester-Camden-Salem Medical Examiner, Sewell, New Jersey autopsy report, the cause of the pilot's death was multiple injuries and the manner of death was accident.

Toxicology testing performed by the Federal Aviation Administration Bioaeronautical Sciences Research Branch detected VALSARTAN, ATORVASTATIN and QUININE. All of these medications would be acceptable for FAA medical certification and are not considered impairing.

<end>