

NATIONAL TRANSPORTATION SAFETY BOARD

NTSB Form 6120.1

PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

Email the pilot/operator aircraft accident/incident report to the investigator-in-charge of your accident/incident. If email is not available, mail the report per the instructions below.

If your accident/incident occurred in Maine, Vermont, New Hampshire, Massachusetts, Connecticut, Rhode Island, New York, New Jersey, Pennsylvania, Maryland, Delaware, Virginia, West Virginia, Kentucky, Tennessee, North Carolina, South Carolina, Mississippi, Alabama, Georgia, Florida, the District of Columbia, Puerto Rico, or the US Virgin Islands, send the form to: NTSB, ERA, 45065 Riverside Parkway, Ashburn, VA 20147.

If your accident/incident occurred in Ohio, Michigan, Indiana, Wisconsin, Illinois, Minnesota, Iowa, Missouri, Arkansas, Louisiana, North Dakota, South Dakota, Nebraska, Kansas, Oklahoma, Texas, Colorado, or New Mexico, send the form to: NTSB, CEN, 4760 Oakland Street, Suite 500, Denver, CO 80239.

If your accident/incident occurred in Montana, Wyoming, Idaho, Utah, Arizona, Nevada, Washington, Oregon, California, Hawaii, or the territories of Guam or American Samoa, send the form to: NTSB, WPR, 505 South 336th Street, Suite 540, Federal Way, WA 98003.

If your accident/incident occurred in Alaska, send the form to: NTSB, ANC, 222 West 7th Avenue, Room 216, Box 11, Anchorage, AK 99513.

Rules pertaining to notification of aircraft accidents and incidents, as well as overdue aircraft are found in 49 *Code of Federal Regulations* (CFR) Part 830 http://www.ecfr.gov/cgi-bin/text-idx?c=ecfr&tpl=/ecfrbrowse/Title49/49cfr830_main_02.tpl. These rules state the authority of the NTSB, define accidents, incidents, injuries, and other terms, and provide procedures for initial and immediate notification of accidents and incidents by aircraft pilots/operators.

A. APPLICABILITY

The pilot/operator of an aircraft shall send a report to the office listed above, based on accident/incident location; immediate notification is required by 49 CFR 830.5(a). **The report shall be filed within 10 days after an accident for which notification is required by Section 830.5, or after 7 days if an overdue aircraft is still missing.**

An aircraft accident, as defined in 49 CFR 830.2, is determined as an occurrence that involves a fatality or serious injury, or substantial damage to the aircraft. For occurrences that do not involve a fatality, the determination that the occurrence is an accident can be appealed by writing to the Director, Office of Aviation Safety, NTSB, 490 L'Enfant Plaza, S.W., Washington, D.C. 20594.

INSTRUCTIONS TO PILOTS/OPERATORS FOR COMPLETING THIS FORM

It is necessary that ALL questions on this report be answered completely and accurately.

If more space is needed, continue on a blank sheet of paper.

Nearest City/Place: Use the name of the nearest community in the state where the accident/incident occurred.

Date/Time: Indicate the date and local time of the event. Be sure to indicate the time zone.

Phase of Operation: Indicate the phase of operation during which the accident/incident occurred.

Aircraft Information: Enter aircraft make and model information as indicated on the aircraft registration certificate, including series. If the involved aircraft is certified as "amateur-built," include the name of the producer of the kit or plans, unless an NTSB employee instructs otherwise.

Maximum Gross Weight: Enter the certificated maximum gross weight for the aircraft involved in the occurrence. This should be the same as the maximum gross weight indicated on the aircraft weight and balance documents.

Engine: Enter engine make and model information as indicated on the engine data plate.

The NTSB uses this form for aircraft accident prevention activities and for statistical purposes. NTSB regulations (49 CFR Part 830) require that ALL questions be answered completely and accurately. Completion of this form will take approximately 60 minutes. The NTSB does not guarantee the privacy of any information provided in this form. You need not complete this form unless it displays a valid OMB control number, in accordance with 5 C.F.R. § 1320.5(b), which applies to this collection of information.

B. DEFINITIONS

1. "Aircraft Accident" means an occurrence associated with the operation of an aircraft that takes place between the time any person boards the aircraft with the intention of flight and all such persons have disembarked, and in which any person suffers death, or serious injury, or in which the aircraft receives substantial damage. For purposes of this form, the definition of "aircraft accident" includes "unmanned aircraft accident," as defined at 49 CFR 830.2.

2. "Substantial Damage" means damage or failure that adversely affects the structural strength, performance or flight characteristics of the aircraft, and that would normally require major repair or replacement of the affected component. NOTE: Engine failure or damage limited to an engine if only one engine fails or is damaged, bent fairing or cowling, dented skin, small puncture holes in the skin or fabric, ground damage to rotor or propeller blades, and damage to landing gear, wheels, tires, flaps, engine accessories, brakes, or wing tips are not considered "substantial damage" for purposes of this report.

3. "Operator" means any person who causes or authorizes the operation of an aircraft, such as the owner, lessee, or bailee of an aircraft.

4. "Fatal Injury" means any injury that results in death within thirty (30) days of the accident.

5. "Serious Injury" means any injury that (1) requires hospitalization for more than 48 hours, commencing within 7 days from the date the injury was received; (2) results in a fracture of any bone (except simple fracture of fingers, toes, or nose); (3) causes severe hemorrhages, nerve, muscle, or tendon damage; (4) involves injury to any internal organ; or (5) involves second- or third-degree burns, or any burns affecting more than 5 percent of the body surface.

Type of Fire Extinguishing System: If a fire extinguishing system was used to fight an aircraft fire, specify the type(s) of extinguishing system(s) used. Examples include handheld extinguisher, engine fire bottle, cargo/baggage compartment fire suppression system, or airport emergency ground equipment.

Owner/Operator Information: Enter the owner information as shown on the registration certificate. Commercial operators, enter the operator information, including "doing business as" when applicable, as shown on the operator certificate.

Revenue Sightseeing Flight: Indicate whether the accident aircraft was conducting revenue sightseeing operations under 14 CFR Part 91 at the time of the accident.

Air Medical Flight: Indicate whether the accident flight was being conducted for the purpose of carrying medical personnel, patient(s), or organs.

Public Aircraft: Federal, state or local government flight operations such as official travel, law-enforcement, low-level observation, aerial application, firefighting, search and rescue, biological or geological resource management, or aeronautical research. Indicate whether the flight was conducted by the armed forces, federal, state, or local government.

Purpose of Flight: 14 CFR Parts 91, 103, 133, 136, and 137: Indicate the type of operation that was being conducted at the time of the occurrence using the following definitions:

AERIAL APPLICATION—Operations using an aircraft to perform aerial application or dispersion of any substance. Examples include agricultural, health, forestry, cloud seeding, firefighting, insect control, etc.

AERIAL OBSERVATION—These flights include aerial mapping/photography, patrol, search and rescue, hunting, highway traffic advisory, ranching, surveillance, oil and mineral exploration, criminal pursuit, fish spotting, etc.

AIR DROP—Aerial operations, other than aerial application, that are intended to release items in flight.

AIR RACE/SHOW—Includes any flight operations conducted as part of an organized air race or public demonstration.

BUSINESS—includes all personal flying without a paid professional crew for reasons associated with furthering a business, including transportation to and from business meetings or work. This does not include corporate/executive operations, air taxi, or commuter operations.

EXECUTIVE/CORPORATE—Company flying with a paid, professional crew.

FERRY—Non-revenue flight under a special flight or "ferry" permit. Refer to 14 CFR 21.197 for details of special flight permit issuance.

FLIGHT TEST—Flight for the purpose of investigating the flight characteristics of an aircraft/aircraft component or evaluating an applicant for a pilot certificate or rating.

INSTRUCTIONAL—Flying while under the supervision of a flight instructor or receiving air carrier training. Personal proficiency flight operations and personal flight reviews, as required by federal air regulations, are excluded.

OTHER WORK USE—Miscellaneous flight operations conducted for compensation or hire such as construction work (not 14 CFR Part 135 operation), parachuting, aerial advertising, towing gliders, etc.

PERSONAL—Flying for personal reasons (excludes business transportation) including pleasure or personal transportation. This also includes practice or proficiency flights performed under flight instructor supervision and not part of an approved flight training program.

POSITIONING—Non-revenue flight conducted for the primary purpose of relocating the aircraft. Examples include moving the aircraft to a maintenance facility or to load passengers or cargo etc.

UNKNOWN—Use only if the primary purpose of flight is not known.

Other Aircraft—Collision: For all accidents involving a collision with another aircraft, including parked aircraft, check "Collision with other aircraft" under Basic Information and complete this section indicating details about the OTHER aircraft involved in the collision.

Airport Information: Complete this section if the accident/incident occurred on approach, landing, takeoff, departure, or within 3 statute miles of an airport. Please refer to the FAA Airport/Facility Directory or other official source for airport information.

Airport Identifier: Provide the official 3 or 4 character airport identifier number.

Runway: Indicate the number of the runway used, including L, R, or C if applicable.

Runway/Landing Surface: Indicate the type of intended runway/landing surface (do not indicate surface conditions). If the surface type was mixed, check all that apply.

Condition of Runway/Landing Surface: Indicate the condition of the intended runway/landing surface. If multiple conditions existed at the time of the accident, check all that apply.

Weather Information at the Accident/Incident Site: Indicate the weather conditions reported at the accident/incident site at the time of occurrence. If no weather reporting was available for the accident/incident site, indicate the reported conditions at the nearest reporting site. Specify the weather reporting site identifier, the observation time, and distance from the accident/incident.

Sky/Lowest Cloud Condition: Indicate the height above ground level of the lowest cloud condition present at the time of the accident/incident and whether coverage was reported as few, scattered, broken or overcast. Also indicate the height above ground level and coverage of the lowest cloud ceiling present at the time of the accident/incident (reported as broken or overcast).

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs: Describe all NOTAMs (distant (D) or Flight Data Center (FDC), if known), AIRMETs, SIGMETs, and PIREPs in effect near the accident/incident.

Flight Crewmember Information: Indicate the category that best describes the capacity served by this flight crewmember at the time of the accident. The designators "Flight Crewmember 1" and "Flight Crewmember 2" do not refer to a specific pilot position or responsibility. If more than one pilot is aboard, they may be entered in any order and their capacity entered as appropriate.

Degree of Injury: See Definitions on the top half of Page 1 of the instructions. Minor injury is not defined. If an injury does not meet the criteria for another injury category, select Minor.

Date of Last Flight Review or Equivalent: Enter the date of the most recent flight review, or equivalent, completed by this pilot. Refer to 14 CFR 61.56 for accepted equivalents.

Type Ratings: List all type ratings on the pilot certificate. If the pilot holds no type ratings indicate "none." If the pilot holds a pilot certificate other than student and was flying an aircraft requiring an endorsement, enter the type and date of any logbook endorsement(s) for that aircraft. See 14 CFR 61 for examples of required endorsements.

Student Endorsements: If the pilot holds a student pilot certificate, enter all solo endorsements and dates on the student pilot certificate.

Flight Time: Complete the flight time matrix. Solo flight time should be included as "Pilot-in-Command (PIC)" and all dual flight instruction given should be included as "Time as Instructor."

Additional Flight Crewmembers: Complete this section if there were more than two required flight crewmembers on the aircraft. This also includes a check airman performing official duties but does not include cabin crew. State the capacity served by each included crewmember at the time of the accident.

Passenger(s)/Other Personnel: Enter identification and injury severity information for all passengers, cabin crew, and other personnel involved in the accident. See Page 1 of the instructions for the official definition of injury levels.

Several questions throughout the form allow for multiple responses; when appropriate, choose all responses that apply.

These instructions only pertain to major issue areas covered by NTSB Form 6120.1 *Pilot/Operator Aircraft Accident/Incident Report*. For additional definitions of questions and responses, please refer to www.nts.gov.

NATIONAL TRANSPORTATION SAFETY BOARD
PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT
 This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Indian Head State: MD
 ZIP: 20640 Country: United States
 Latitude: 38-35-49.3750N Longitude: 077-04-20.8500W
 (Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 02/17/2021 Local Time: 9:45
 mm/dd/yyyy Time Zone: EST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N8428J

Manufacturer: Cessna

Model: 150G

Serial Number: 15066328

Year of Manufacture: 1967

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 1600 lbs

Weight at Time of Accident/Incident: ~1500 lbs

Number of Seats: 2 Flight Crew Seats: 1

Cabin Crew Seats: 0 Passenger Seats: 1

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate
 (Check all that apply)

Standard

- ☒ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle
- ☐ Amphibian
- ☐ Emergency Float
- ☐ Float
- ☐ Hull
- ☐ Other Launch/Recovery System
- ☐ None
- ☐ Tailwheel
- ☐ High Skid
- ☐ Skid
- ☐ Ski
- ☐ Ski/Wheel
- ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating
- ☐ Turbo Shaft
- ☐ Turbo Prop
- ☐ Turbo Jet
- ☐ Turbo Fan
- ☐ Electric
- ☐ Liquid Rocket
- ☐ Solid Rocket
- ☐ Hybrid Rocket
- ☐ None
- ☐ Unknown

Fuel System Type (Reciprocating)

- ☐ Carburetor
- ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Continental	O-200-A	Provided By owner	Provided by	100	~4300	~25	~870
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour
- ☐ AAIP
- ☒ Annual
- ☐ Continuous Airworthiness
- ☐ Conditional Inspection
- ☐ Unknown

Date Last Inspection: 05/09/2020
 mm/dd/yyyy

Airframe Total Time: ~6380 hrs
 hours measured at (Select one)

☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
- ☒ Specify: Owner Provided

Propeller 1

- ☒ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Owner Provided

Model: Owner Provided

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____
 Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: ACK Technologies

Model or Part No.: E04M

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft: ☐ Yes ☒ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☐ Autopilot
- ☐ Data Recorder
- ☒ Electronic Flight Bag or Handheld Device
- ☐ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☐ Onboard Weather
- ☐ Satellite Tracking Device
- ☐ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Timothy CoteCity: WashingtonFractional Ownership Aircraft: ☐ Yes ☒ NoState: DCZIP: 20008Country: United States**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____

ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

☐ Public Aircraft (Select one)

- ☐ Armed Forces
☐ Federal
☐ State
☐ Local

☐ Unknown**Revenue Operation for FAR 121, 125, 129, 135**

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☒ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Maryland AirportDistance From Airport Center: 3 smAirport Identifier: 2W5Direction From Airport: 170 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 175 ft. msl**Runway Information**Runway ID: 20 (L/R/C) Length: 3740 ft Width: 75 ft**Condition of Runway/Landing Surface** (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Runway/Landing Surface (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi
Takeoff
Initial Climb
- VFR Departure
IFR Departure Procedure/Clearance
- On Instrument Approach
☐ Landing
- ☐ Downwind
☐ Base
☐ Final
☐ Crosswind
- ☐ Low Approach
☒ Go Around
☐ Aborted Landing (after touchdown)
☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☐ Pilot ☐ Co-Pilot ☐ Student Pilot ☒ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☐ Yes ☒ No

"Flight Crewmember 1" Identification

First Name: Katrina

Middle Initial: F

Last Name: Emery

City of Residence: McLean

State: VA

ZIP: 22102

Country: United States

Age at time of Accident/Incident: 35

Date of Birth:

mm/dd/yyyy

Certificate Number:

Degree of Injury

☒ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☒ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☒ Flight Instructor ☒ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☒ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☒ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

10/05/2020
mm/dd/yyyy

Medical Certificate Limitations

Corrective Lenses (Pilot was wearing at time of accident)

Medical Certificate Special Issuance

N/A

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

01/30/2021
mm/dd/yyyy

Flight Review Aircraft

Make: Piper

Model: Seminole

Airplane Rating(s) (Check all that apply)

☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None
☒ Airplane Single-Engine
☐ Airplane Multi-Engine
☐ Gyroplane
☐ Powered Lift
☒ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings

None

Student Endorsements (Include dates)

N/A

Flight Time (Enter appropriate number of hours in each box)

	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	1,221	25	1,144	33	100	85	72			
Pilot in Command (PIC)	1,147	25	1,145	2	75	85	0			
Time as Instructor	877	25	877	0	62	83	0			
This Make/Model					0	0	0			
Last 90 Days	115	25	115	33	6	8	2			
Last 30 Days	15	23	15	0	4	2	0			
Last 24 Hours	0	0	0	0	0	0	0			

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☒ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☒ Yes ☐ No

“Flight Crewmember 2” Identification

First Name: Timothy

City of Residence: Washington

Middle Initial: R

State: DC ZIP: 20008

Last Name: Cote

Country: United States

Age at time of Accident/Incident: 60 Date of Birth: mm/dd/yyyy

Certificate Number: _____ Unknown

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available	Used
☐ None	☐ None
☐ Lap only	☐ Lap only
☐ 3-point	☐ 3-point
☐ 4-point	☐ 4-point
☐ 5-point	☐ 5-point
☐ Unknown	☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☐ Commercial
 ☐ US Military

☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign

☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

**Date of Last Flight Review
or Equivalent, Including
FAR 121/135 Checks:**

mm/dd/yyyy

Flight Review Aircraft

Make:

Model:

Airplane Rating(s)
(Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)
(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)
(Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)
(Check all that apply)

☐ None

☐ Airplane Single-Engine

☐ Airplane Multi-Engine

☐ Gyroplane

☐ Powered Lift

☐ Instrument Airplane

☐ Instrument Helicopter

☐ Helicopter

☐ Glider

☐ Sport

Type Ratings

Student Endorsements *(Include dates)*

[illegible]

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)

Crew Name and Address

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

Seat Occupied

☐ Left ☐ Front
☐ Center ☐ Rear
☐ Right ☐ Single
☐ Unknown ☐ Unknown

Injury

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Restraint Type:

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Type Rating/Endorsement for

Accident/Incident Aircraft? ☐ Yes ☐ No

Total Flight Time at the Time

of this Accident/Incident: _____ hrs

Crew Name and Address

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

Seat Occupied

☐ Left ☐ Front
☐ Center ☐ Rear
☐ Right ☐ Single
☐ Unknown ☐ Unknown

Injury

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Restraint Type:

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Type Rating/Endorsement for

Accident/Incident Aircraft? ☐ Yes ☐ No

Total Flight Time at the Time

of this Accident/Incident: _____ hrs

PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)

Name and Address

First Name: _____ City: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

☐ Crew ☐ Passenger ☐ Other

Seat

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

Injury

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Restraint Type

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Age

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

First Name: _____ City: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

☐ Crew ☐ Passenger ☐ Other

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

First Name: _____ City: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

☐ Crew ☐ Passenger ☐ Other

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

First Name: _____ City: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

☐ Crew ☐ Passenger ☐ Other

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: KVKX

City: Fort Washington

State: MD

Country: United States

Time of Departure

Time: 8:15

Time Zone: EST

Destination

Airport ID: 2W5

City: Indian Head

State: MD

Country: United States

Type Flight Plan Filed

- ☐ None ☒ VFR/IFR
☐ Company VFR ☐ IFR
☐ Military VFR ☐ Unknown
☐ VFR

Activated? ☒ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

- ☐ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☒ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

- ☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☐ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence:

300 ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

- ☐ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☐ Internet
☒ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☐ On-Board Weather

Weather Observation Facility

Facility ID: KDAA

Observation Time: 9:30

Time Zone: EST

Distance from Accident Site: 9 nm

Direction from Accident Site: 155 degrees true

Basic Conditions

- ☒ VMC
☐ IMC
☐ Unknown

Light Condition

- ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

- ☐ Clear ☐ Thin Broken
☒ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

12000 ft agl

Ceiling

- ☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

 ft agl

Temperature: -7 (C) or (F)

Dew Point: -10 (C) or (F)

Altimeter Setting: 30.30 in. Hg
or MB

Wind Direction

- ☒ Variable

-or-
Direction: degrees true

Wind Speed

- ☐ Calm
☒ Light and Variable

-or-
Speed: kts

Wind Gusts

- ☒ Not Gusting

-or-
Speed: kts

Visibility 30 miles

RVR: feet

RVV: miles

Density Altitude: ft

Intensity of Precipitation

- ☐ Light
☐ Moderate
☐ Heavy
☐ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

- ☒ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

- ☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

- Amount Type
☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Icing Actual

- Amount Type
☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Turbulence

- Type (Check all that apply) Severity
☒ None ☐ Light
☐ Clear Air ☐ Moderate
☐ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

Airspace (FRZ, SFRA), Obstructions.

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☒ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Aircraft totaled, wings crumpled, vertical stabler twisted/crushed, nose gear twisted,

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible.

The incident flight occurred on February 17, 2021, during a final pre-check flight for CFI Candidate Tim Cote.

Mr. Cote hired me to complete a training syllabus provided by DPE Mike Deruggiero and ensure he met CFI PTS to become a CFI. Mr. Cote held a Commercial Multi Engine Pilot's License with Instrument and Sea Plane Rating, and had approximately 800 hours. Mr. Cote also owned a C-150G that was tied down at Potomac Airpark (KVKX) that he wanted to use for his training and CFI Test.

I conducted 10 training flights with Mr. Cote from January 20 to February 10, before the February 17, 2021 incident flight. I followed the FAA Instructors handbook (FAA-H-8083-98) and FAA-S-8081-6D [Flight Instructor PTS], and incorporated the training syllabus and check list provided by DPE Deruggiero. Each lesson began with ground school, mission brief, review of preflight planning and aircraft inspection, followed by the flight and debrief. Each pre-flight inspection was performed with checklist in hand and included measuring fuel in the tanks and sumping each port for BS&W with a GATS fuel jar tester.

By February 10, Mr. Cote had completed Mr. Deruggiero's syllabus and demonstrated compliance with the CFI PTS. We then scheduled a final pre-test flight that would focus on flight performance on February 17, 2021. Mr. Cote would be the pilot-in-command and function as the CFI demonstrating required flight maneuvers from the right seat while I functioned as a Student Pilot in the left seat and monitored his performance.

When I arrived at Potomac Airfield (KVKX) on Wednesday, February 17, 2021, Mr. Cote reported he had obtained a Standard Briefing, filed the FRZ Flight Plan as Pilot-in-Command, and completed the pre-flight inspection. Mr. Cote also stated the tanks were full, but that he had observed some water in the strainer tank, so he drained that tank until fuel from each port was clear blue 100LL. We then reviewed the lesson plan which included Turns Around a Point, S-Turns across a road and Rectangular Patterns, Commercial Maneuvers that included Lazy-Eights, Chandelles and Steep Spirals, and Short and Soft Field Take-Offs and Landings and a Power-Off 180 at 2W5 (Maryland Airpark). This lesson plan followed prior flights, with flight maneuvers to be performed in a practice area located approximately 20 miles south on the 180 radial of the DCA VOR.

Before entering the aircraft, I conducted a walk around that included visual inspections to make sure the fuel caps were secure and oil was normal. Tim sat in the right seat, handled all radio calls, and was the pilot-in-command throughout the flight as briefed.

Engine start was at approximately 0815L. I verified that the fuel gauges indicated full, and observed Tim perform the engine start, taxi and instrument checks. Runup and Mag Checks were normal. Winds were light and variable from East to West, so Tim decided to depart on Runway 24. I agreed.

Tim performed a Normal Take-Off to standards with a ground run of approximately 735 feet, which meet expected performance. We departed to the south/south west to the practice area and began with clearing turns followed by ground reference maneuvers that included Turns around a point, S-Turns and a Rectangular course at 1100-1200 MSL and approximately 90 MPH. Tim performed these maneuvers to standards. We then climbed to approximately 2500 MSL for Commercial maneuvers that began with Lazy Eights. I helped Tim on the first two Lazy Eights, after which he performed several Lazy Eights to commercial standards.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

Not sure the engine stopping could have been prevented. A lower and slower pattern would have allowed for on airport landing.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Continental O-200-A, part/serial/time/cycles provided by owner.

**Total Time/Cycles
On Part**____ Hours
____ Cycles**Time Since This Part
Inspected/Overhauled**

~20 ____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**
(Convert from pounds, as necessary)

26 ____ Gallons

Fuel Type☐ 80/87 ☐ 115/145 ☐ Jet B ☐ Other, specify _____
☒ 100 Low Lead ☐ Jet A ☐ JP8
☐ 100/130 ☐ Jet A-1 ☐ Automotive**Other Services, if Any, Prior to Departure**

None

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☒ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

2 occupants, both exited from right hand door which popped open upon impact

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number****Manufacturer:** _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed ☐ Minor
☐ Substantial ☐ None**Registered Owner of Other Aircraft**Name: _____
City: _____
State: _____ ZIP: _____
Country: _____**Pilot of Other Aircraft**Name: _____
City: _____
State: _____ ZIP: _____
Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

Continued statement

I then asked Tim to explain and perform a Chandelle, then climb to an appropriate altitude for a Steep Spiral. Tim initiated a Chandelle to the left and, as we turned to the 90-degree point, the engine sputtered and seemed to lose power. Tim immediately leveled the airplane while I verified Fuel was On, pulled the Carb Heat, and verified Ignition on Both and Mixture Rich. Tim continued to fly the aircraft with one hand on the throttle and the other on the yoke. I verified that Tach, Oil Temp and Pressure gauges remained steady and in the green, and according to the gauges there was adequate fuel in the tanks. The engine continued to develop power but sounded rough. I believe we were then about 12 SE of 2W5, and recall each of us stating we should fly direct to 2W5 for a precautionary landing. I also suggested that we start a gentle climb to increase altitude in the event of engine failure.

We climbed to approximately 4000 MSL on our way to 2W5 while the engine appeared to develop normal power, but remained rough. As we approached 2W5, I reported field elevation and asked Tim which runway he decided to land and heard him say Runway 20. I verified the windsock to favor 20, and agreed.

Tim made a spiral descent to enter the pattern on a right downwind. I recall looking at my iPad, using Foreflight paired with a Stratux ADS-B receiver, and outside to verify there was no traffic was in the pattern. As Tim turned to a right downwind, I stated we were high and fast, 2000 MSL and 110 MPH. Tim acknowledged my call and reduced power to correct. I continued to look for traffic, and made radio calls on CTAF for downwind, base and final. After Tim turned base, we both stated we were high and needed to slip on final. After Tim turned final, I joined Tim on the flight controls to ensure a full forward slip was achieved for maximum descent on centerline. Our altitude and rate of descent over the threshold appeared accurate, but airspeed was high, which caused the aircraft to float at approximately 10 feet above the runway. As we reached the last third of the runway, Tim declared he would execute a go around. I agreed because the engine had been idling normally and we could not land safely before hitting trees beyond the end of the runway.

Tim applied full power and I believe pushed the Carb Heat in to the Off position. My feet and left hand remained on the flight controls to follow Tim as he pitched to climb at Vy. The engine responded normally until we reached approximately 200 - 300 feet AGL, where it suddenly sputtered and stopped. The propeller windmilled for a couple of seconds and also stopped. I remained on the flight controls with Tim as we pitched to the best glide speed of 65 mph. I scanned for best emergency landing area and said something like we have to land on the trees. He agreed. We executed a full flare landing on the treetops, and continued to fly the plane until it came to a complete stop. The plane then slid down the trees. We both exited the aircraft through the right door and met in front to verify we were both uninjured and to await emergency services.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

03/03/2021

mm/dd/yyyy

Name of Pilot/Operator: Katrina Emery

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.
ERA21LA132

Reviewed by NTSB Regional Office
AS-ERA

Name of Investigator
Lynn Spencer

Date Report Received
3/5/2021

NATIONAL TRANSPORTATION SAFETY BOARD

NTSB Form 6120.1

PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

Email the pilot/operator aircraft accident/incident report to the investigator-in-charge of your accident/incident. If email is not available, mail the report per the instructions below.

If your accident/incident occurred in Maine, Vermont, New Hampshire, Massachusetts, Connecticut, Rhode Island, New York, New Jersey, Pennsylvania, Maryland, Delaware, Virginia, West Virginia, Kentucky, Tennessee, North Carolina, South Carolina, Mississippi, Alabama, Georgia, Florida, the District of Columbia, Puerto Rico, or the US Virgin Islands, send the form to: NTSB, ERA, 45065 Riverside Parkway, Ashburn, VA 20147.

If your accident/incident occurred in Ohio, Michigan, Indiana, Wisconsin, Illinois, Minnesota, Iowa, Missouri, Arkansas, Louisiana, North Dakota, South Dakota, Nebraska, Kansas, Oklahoma, Texas, Colorado, or New Mexico, send the form to: NTSB, CEN, 4760 Oakland Street, Suite 500, Denver, CO 80239.

If your accident/incident occurred in Montana, Wyoming, Idaho, Utah, Arizona, Nevada, Washington, Oregon, California, Hawaii, or the territories of Guam or American Samoa, send the form to: NTSB, WPR, 505 South 336th Street, Suite 540, Federal Way, WA 98003.

If your accident/incident occurred in Alaska, send the form to: NTSB, ANC, 222 West 7th Avenue, Room 216, Box 11, Anchorage, AK 99513.

Rules pertaining to notification of aircraft accidents and incidents, as well as overdue aircraft are found in 49 *Code of Federal Regulations* (CFR) Part 830 http://www.ecfr.gov/cgi-bin/text-idx?c=ecfr&tpl=/ecfrbrowse/Title49/49cfr830_main_02.tpl. These rules state the authority of the NTSB, define accidents, incidents, injuries, and other terms, and provide procedures for initial and immediate notification of accidents and incidents by aircraft pilots/operators.

A. APPLICABILITY

The pilot/operator of an aircraft shall send a report to the office listed above, based on accident/incident location; immediate notification is required by 49 CFR 830.5(a). **The report shall be filed within 10 days after an accident for which notification is required by Section 830.5, or after 7 days if an overdue aircraft is still missing.**

An aircraft accident, as defined in 49 CFR 830.2, is determined as an occurrence that involves a fatality or serious injury, or substantial damage to the aircraft. For occurrences that do not involve a fatality, the determination that the occurrence is an accident can be appealed by writing to the Director, Office of Aviation Safety, NTSB, 490 L'Enfant Plaza, S.W., Washington, D.C. 20594.

INSTRUCTIONS TO PILOTS/OPERATORS FOR COMPLETING THIS FORM

It is necessary that ALL questions on this report be answered completely and accurately.

If more space is needed, continue on a blank sheet of paper.

Nearest City/Place: Use the name of the nearest community in the state where the accident/incident occurred.

Date/Time: Indicate the date and local time of the event. Be sure to indicate the time zone.

Phase of Operation: Indicate the phase of operation during which the accident/incident occurred.

Aircraft Information: Enter aircraft make and model information as indicated on the aircraft registration certificate, including series. If the involved aircraft is certified as "amateur-built," include the name of the producer of the kit or plans, unless an NTSB employee instructs otherwise.

Maximum Gross Weight: Enter the certificated maximum gross weight for the aircraft involved in the occurrence. This should be the same as the maximum gross weight indicated on the aircraft weight and balance documents.

Engine: Enter engine make and model information as indicated on the engine data plate.

The NTSB uses this form for aircraft accident prevention activities and for statistical purposes. NTSB regulations (49 CFR Part 830) require that **ALL** questions be answered completely and accurately. Completion of this form will take approximately 60 minutes. The NTSB does not guarantee the privacy of any information provided in this form. You need not complete this form unless it displays a valid OMB control number, in accordance with 5 C.F.R. § 1320.5(b), which applies to this collection of information.

B. DEFINITIONS

1. "Aircraft Accident" means an occurrence associated with the operation of an aircraft that takes place between the time any person boards the aircraft with the intention of flight and all such persons have disembarked, and in which any person suffers death, or serious injury, or in which the aircraft receives substantial damage. For purposes of this form, the definition of "aircraft accident" includes "unmanned aircraft accident," as defined at 49 CFR 830.2.

2. "Substantial Damage" means damage or failure that adversely affects the structural strength, performance or flight characteristics of the aircraft, and that would normally require major repair or replacement of the affected component. NOTE: Engine failure or damage limited to an engine if only one engine fails or is damaged, bent fairing or cowling, dented skin, small puncture holes in the skin or fabric, ground damage to rotor or propeller blades, and damage to landing gear, wheels, tires, flaps, engine accessories, brakes, or wing tips are not considered "substantial damage" for purposes of this report.

3. "Operator" means any person who causes or authorizes the operation of an aircraft, such as the owner, lessee, or bailee of an aircraft.

4. "Fatal Injury" means any injury that results in death within thirty (30) days of the accident.

5. "Serious Injury" means any injury that (1) requires hospitalization for more than 48 hours, commencing within 7 days from the date the injury was received; (2) results in a fracture of any bone (except simple fracture of fingers, toes, or nose); (3) causes severe hemorrhages, nerve, muscle, or tendon damage; (4) involves injury to any internal organ; or (5) involves second- or third-degree burns, or any burns affecting more than 5 percent of the body surface.

Type of Fire Extinguishing System: If a fire extinguishing system was used to fight an aircraft fire, specify the type(s) of extinguishing system(s) used. Examples include handheld extinguisher, engine fire bottle, cargo/baggage compartment fire suppression system, or airport emergency ground equipment.

Owner/Operator Information: Enter the owner information as shown on the registration certificate. Commercial operators, enter the operator information, including "doing business as" when applicable, as shown on the operator certificate.

Revenue Sightseeing Flight: Indicate whether the accident aircraft was conducting revenue sightseeing operations under 14 CFR Part 91 at the time of the accident.

Air Medical Flight: Indicate whether the accident flight was being conducted for the purpose of carrying medical personnel, patient(s), or organs.

Public Aircraft: Federal, state or local government flight operations such as official travel, law-enforcement, low-level observation, aerial application, firefighting, search and rescue, biological or geological resource management, or aeronautical research. Indicate whether the flight was conducted by the armed forces, federal, state, or local government.

Purpose of Flight: 14 CFR Parts 91, 103, 133, 136, and 137: Indicate the type of operation that was being conducted at the time of the occurrence using the following definitions:

AERIAL APPLICATION—Operations using an aircraft to perform aerial application or dispersion of any substance. Examples include agricultural, health, forestry, cloud seeding, firefighting, insect control, etc.

AERIAL OBSERVATION—These flights include aerial mapping/photography, patrol, search and rescue, hunting, highway traffic advisory, ranching, surveillance, oil and mineral exploration, criminal pursuit, fish spotting, etc.

AIR DROP—Aerial operations, other than aerial application, that are intended to release items in flight.

AIR RACE/SHOW—Includes any flight operations conducted as part of an organized air race or public demonstration.

BUSINESS—includes all personal flying without a paid professional crew for reasons associated with furthering a business, including transportation to and from business meetings or work. This does not include corporate/executive operations, air taxi, or commuter operations.

EXECUTIVE/CORPORATE—Company flying with a paid, professional crew.

FERRY—Non-revenue flight under a special flight or "ferry" permit. Refer to 14 CFR 21.197 for details of special flight permit issuance.

FLIGHT TEST—Flight for the purpose of investigating the flight characteristics of an aircraft/aircraft component or evaluating an applicant for a pilot certificate or rating.

INSTRUCTIONAL—Flying while under the supervision of a flight instructor or receiving air carrier training. Personal proficiency flight operations and personal flight reviews, as required by federal air regulations, are excluded.

OTHER WORK USE—Miscellaneous flight operations conducted for compensation or hire such as construction work (not 14 CFR Part 135 operation), parachuting, aerial advertising, towing gliders, etc.

PERSONAL—Flying for personal reasons (excludes business transportation) including pleasure or personal transportation. This also includes practice or proficiency flights performed under flight instructor supervision and not part of an approved flight training program.

POSITIONING—Non-revenue flight conducted for the primary purpose of relocating the aircraft. Examples include moving the aircraft to a maintenance facility or to load passengers or cargo etc.

UNKNOWN—Use only if the primary purpose of flight is not known.

Other Aircraft—Collision: For all accidents involving a collision with another aircraft, including parked aircraft, check "Collision with other aircraft" under Basic Information and complete this section indicating details about the OTHER aircraft involved in the collision.

Airport Information: Complete this section if the accident/incident occurred on approach, landing, takeoff, departure, or within 3 statute miles of an airport. Please refer to the FAA Airport/Facility Directory or other official source for airport information.

Airport Identifier: Provide the official 3 or 4 character airport identifier number.

Runway: Indicate the number of the runway used, including L, R, or C if applicable.

Runway/Landing Surface: Indicate the type of intended runway/landing surface (do not indicate surface conditions). If the surface type was mixed, check all that apply.

Condition of Runway/Landing Surface: Indicate the condition of the intended runway/landing surface. If multiple conditions existed at the time of the accident, check all that apply.

Weather Information at the Accident/Incident Site: Indicate the weather conditions reported at the accident/incident site at the time of occurrence. If no weather reporting was available for the accident/incident site, indicate the reported conditions at the nearest reporting site. Specify the weather reporting site identifier, the observation time, and distance from the accident/incident.

Sky/Lowest Cloud Condition: Indicate the height above ground level of the lowest cloud condition present at the time of the accident/incident and whether coverage was reported as few, scattered, broken or overcast. Also indicate the height above ground level and coverage of the lowest cloud ceiling present at the time of the accident/incident (reported as broken or overcast).

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs: Describe all NOTAMs (distant (D) or Flight Data Center (FDC), if known), AIRMETs, SIGMETs, and PIREPs in effect near the accident/incident.

Flight Crewmember Information: Indicate the category that best describes the capacity served by this flight crewmember at the time of the accident. The designators "Flight Crewmember 1" and "Flight Crewmember 2" do not refer to a specific pilot position or responsibility. If more than one pilot is aboard, they may be entered in any order and their capacity entered as appropriate.

Degree of Injury: See Definitions on the top half of Page 1 of the instructions. Minor injury is not defined. If an injury does not meet the criteria for another injury category, select Minor.

Date of Last Flight Review or Equivalent: Enter the date of the most recent flight review, or equivalent, completed by this pilot. Refer to 14 CFR 61.56 for accepted equivalents.

Type Ratings: List all type ratings on the pilot certificate. If the pilot holds no type ratings indicate "none." If the pilot holds a pilot certificate other than student and was flying an aircraft requiring an endorsement, enter the type and date of any logbook endorsement(s) for that aircraft. See 14 CFR 61 for examples of required endorsements.

Student Endorsements: If the pilot holds a student pilot certificate, enter all solo endorsements and dates on the student pilot certificate.

Flight Time: Complete the flight time matrix. Solo flight time should be included as "Pilot-in-Command (PIC)" and all dual flight instruction given should be included as "Time as Instructor."

Additional Flight Crewmembers: Complete this section if there were more than two required flight crewmembers on the aircraft. This also includes a check airman performing official duties but does not include cabin crew. State the capacity served by each included crewmember at the time of the accident.

Passenger(s)/Other Personnel: Enter identification and injury severity information for all passengers, cabin crew, and other personnel involved in the accident. See Page 1 of the instructions for the official definition of injury levels.

Several questions throughout the form allow for multiple responses; when appropriate, choose all responses that apply.

These instructions only pertain to major issue areas covered by NTSB Form 6120.1 Pilot/Operator Aircraft Accident/Incident Report. For additional definitions of questions and responses, please refer to www.nts.gov.

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Indian Head State: MD

ZIP: _____ Country: Charles County

Latitude: _____ Longitude: _____

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 02/17/2021 Local Time: 9:30am

mm/dd/yyyy

Time Zone: Eastern

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☐ None

AIRCRAFT INFORMATION

Registration Number: N8428J

Manufacturer: Cessna

Model: 150

Serial Number: 150-66328

Year of Manufacture: _____

Amateur-Built: ☒ Yes ☐ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☐ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 1600 lbs

Weight at Time of Accident/Incident: 1500 lbs

Number of Seats: 2 Flight Crew Seats: 2

Cabin Crew Seats: 0 Passenger Seats: 0

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

☒ Tricycle

☐ Tailwheel

☐ Amphibian

☐ High Skid

☐ Emergency Float

☐ Skid

☐ Float

☐ Ski

☐ Hull

☐ Ski/Wheel

☐ Other Launch/Recovery System

☐ None

☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating
- ☐ Liquid Rocket
- ☐ Turbo Shaft
- ☐ Solid Rocket
- ☐ Turbo Prop
- ☐ Hybrid Rocket
- ☐ Turbo Jet
- ☐ None
- ☐ Turbo Fan
- ☐ Unknown
- ☐ Electric

Fuel System Type (Reciprocating)

☐ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. <i>mm/dd/yyyy</i>	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Continental	o-200A	250397-A-48		100	4275.8	30	847.8
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour
- ☐ AAIP
- ☒ Annual
- ☐ Continuous Airworthiness
- ☐ Conditional Inspection
- ☐ Unknown

Date Last Inspection: 05/09/2020

mm/dd/yyyy

Airframe Total Time: 6366.14 hrs

hours measured at (Select one)

☒ Last Inspection ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
- ☒ Specify: _____

Propeller 1

- ☒ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: McCaulley

Model: 1A101

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: ACK

Model or Part No.: 04

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)

☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft: ☐ Yes ☒ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☐ Autopilot
- ☐ Data Recorder
- ☒ Electronic Flight Bag or Handheld Device
- ☐ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☐ Onboard Weather
- ☐ Satellite Tracking Device
- ☐ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Cote Holding LLCCity: WashingtonState: DCZIP: 20008Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: USA**Operator of Aircraft**☒ Same As Registered Owner☐ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____

ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☒ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Maryland AirportDistance From Airport Center: 2.5 smAirport Identifier: 2W5Direction From Airport: South East degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 100 ft. msl**Runway Information**Runway ID: 20 (L/R/C) Length: 3740 ft Width: 75 ft**Condition of Runway/Landing Surface** (Check all that apply)**Runway/Landing Surface** (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☒ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Crosswind ☐ Aborted Landing (after touchdown)
☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☒ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☐ Pilot ☐ Co-Pilot ☐ Student Pilot ☒ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Katrina City of Residence: _____
 Middle Initial: F State: VA ZIP: _____
 Last Name: Emery Country: _____
 Age at time of Accident/Incident: 32 Date of Birth: _____ mm/dd/yyyy

Certificate Number:

Degree of Injury

☒ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☒ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available	Used
☐ None	☐ None
☐ Lap only	☐ Lap only
☐ 3-point	☐ 3-point
☒ 4-point	☒ 4-point
☐ 5-point	☐ 5-point
☐ Unknown	☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☒ Flight Instructor ☒ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

“Flight Crewmember 2” Responsibilities at the Time of Accident/Incident

☐ Pilot ☐ Co-Pilot ☒ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

First Name: Timothy

City of Residence: Washington

Middle Initial: R

State: DC ZIP: 20008

Last Name: Cote

Country: USA

Age at time of Accident/Incident: 60 Date of Birth: [REDACTED] mm/dd/yyyy

Certificate Number: [REDACTED]

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious		Seat Occupied ☐ Left ☐ Front ☐ Unknown ☒ Right ☐ Rear ☐ Center ☐ Single		Restraint Type Available ☐ None ☐ Lap only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Pilot Certificate(s) <i>(Check all that apply)</i> ☐ None ☐ Flight Instructor ☒ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer						
Principal Occupation ☐ Pilot ☐ Other ☐ Unknown		Medical Certificate ☐ None ☐ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☒ Class 2 ☐ Unknown		Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance		
				Date of Last Medical <u>02/06/2020</u> <i>mm/dd/yyyy</i>		

Must wear correctivew lenses

**Date of Last Flight Review
or Equivalent, Including
FAR 121/135 Checks:**

03/10/2020

mm/dd/yyyy

Make: Cessna

Model: 206 amphibious

Airplane Rating(s) (Check all that apply)	Other Aircraft Rating(s) (Check all that apply)	Instrument Rating(s) (Check all that apply)	Instructor Rating(s) (Check all that apply)
☐ None ☒ Single-Engine Land ☒ Single-Engine Sea ☒ Multiengine Land ☐ Multiengine Sea	☒ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	☒ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport

none

Student Endorsements *(Include dates)*

Flight Time <i>(Enter appropriate number of hours in each box)</i>	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	838	24	432	170	6					
Pilot in Command (PIC)	734	4	484	150						
Time as Instructor										
This Make/Model										
Last 90 Days		22								
Last 30 Days		18								
Last 24 Hours		0								

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)

Crew Name and Address		Seat Occupied	Injury
First Name: _____	City of Residence: _____	☐ Left ☐ Center ☐ Right	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Middle Initial: _____	State: _____ ZIP: _____	☐ Front ☐ Rear ☐ Single ☐ Unknown	
Last Name: _____	Country: _____		
Pilot Certificate(s) (Check all that apply)		Restraint Type:	Inflatable Restraints
☐ None ☐ Private ☐ Student	☐ Flight Instructor ☐ Recreational ☐ Sport	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown
☐ Commercial ☐ Airline Transport ☐ Flight Engineer			☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs	

Crew Name and Address		Seat Occupied	Injury
First Name: _____	City of Residence: _____	☐ Left ☐ Center ☐ Right	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Middle Initial: _____	State: _____ ZIP: _____	☐ Front ☐ Rear ☐ Single ☐ Unknown	
Last Name: _____	Country: _____		
Pilot Certificate(s) (Check all that apply)		Restraint Type:	Inflatable Restraints
☐ None ☐ Private ☐ Student	☐ Flight Instructor ☐ Recreational ☐ Sport	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown
☐ Commercial ☐ Airline Transport ☐ Flight Engineer			☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs	

PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)

Name and Address	Seat	Injury	Restraint Type	Inflatable Restraints	Age
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: KVKX
City: Friendly
State: MD
Country: USA

Time of Departure

Time: 8am
Time Zone: EST

Destination

Airport ID: 2W5
City: Indian Head
State: MD
Country: USA

Type Flight Plan Filed

☐ None ☐ VFR/IFR
☐ Company VFR ☒ IFR
☐ Military VFR ☐ Unknown
☐ VFR
Activated? ☐ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

☐ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☐ VFR ☐ IFR ☐ VFR On Top ☒ Traffic Advisory ☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☒ Class E ☐ Restricted Area ☐ FAR 93
Altitude of In-Flight Occurrence: 400 ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☒ National Weather Service ☐ Company
☒ Flight Service Station ☐ Military
☐ TV/Radio ☐ Internet
☐ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☒ On-Board Weather

Weather Observation Facility

Facility ID: Foreflight
Observation Time: _____
Time Zone: _____
Distance from Accident Site: _____ nm
Direction from Accident Site: _____ degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Temperature: _____ (C) or 30 (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: _____ in. Hg
or _____ MB

Lowest Cloud Condition Height

_____ ft agl

Ceiling Height

_____ ft agl

Wind Direction

☐ Variable

-or-

Direction: _____ degrees true

Wind Speed

☐ Calm
☒ Light and Variable

-or-

Speed: _____ kts

Wind Gusts

☐ Not Gusting

-or-

Speed: _____ kts

Visibility 20 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☐ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☐ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount

☒ None
☐ Trace
☐ Light
☐ Moderate
☐ Severe
☐ Unknown

Type

☐ N/A
☐ Rime
☐ Clear
☐ Mixed
☐ Unknown

Icing Actual

Amount

☒ None
☐ Trace
☐ Light
☐ Moderate
☐ Severe
☐ Unknown

Type

☐ N/A
☐ Rime
☐ Clear
☐ Mixed
☐ Unknown

Turbulence

Type (Check all that apply)

☒ None
☐ Clear Air
☐ Terrain-Induced
☐ Convective Turbulence

Severity

☐ Light
☐ Moderate
☐ Severe
☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

none

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property (Use additional sheet if necessary)

completely destroyed

NARRATIVE HISTORY OF FLIGHT (Please type or print in ink)

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

Flight of N8428J Feb 17, 2021

N8428J is a Cessna 150 (C150) owned since June 2016 by Timothy Cote and intended as a trainer for himself to become a Certified Flight Instructor (CFI) and to teach aviation to teenagers. Timothy Cote employed Ms. Katrina Emery CFI to aid his preparation for the flight instructor rating. Timothy Cote is an instrument rated Commercial pilot with 838.5hr of flight time, of which only 21.9hrs are in the C150. Most of Cote's C150 hours (15.3) were accrued since the beginning of 2021, and the vast majority of these were accrued with Ms. Emery.

Prior to the events of Feb 17, the single most persistent squak in the plane was the repeated accumulation of water in the right wing. Mr Cote reported this to his A/P, Mr. Timothy Poole on the field at KVKX where the plane is based on a tie down, and Mr. Pool advised replacing the tank fill cap gaskets, which he did several weeks prior to Feb 17. Mr. Cote scrupulously sumped both tanks and the belly drain from the plane before each flight, and regularly rocked the wings to disrupt any water that might pool behind any wrinkle in either bladder tank. Subsequent to the gasket replacement, water was still sometimes found from the right tank or the belly drain however, it was relatively easy to clear this with repeated sumps.

On the morning of Feb 17 Mr Cote filled gas on both sides and sumped both tanks and the belly drain—the left tank had fuel only, the right tank had fuel only but dribbled slowly. At the belly drain, half the first tube was filled with water, however this disappeared and was fuel only in subsequent tube samples taken after 20sec of drainage. The wings were rocked, all drainage ports were retested and found to have only fuel without water contamination. Ms Emery was advised. The engine had 5 quarts of oil, above the minimum 4 quarts required. Other preflight operations were unremarkable.

Cote and Emery departed from KVKX, Cote in right seat, Emery in left. The first 60-90min of the flight were a collection of maneuvers in preparation for Cote's upcoming CFI checkride: Lazy 8s, turns around rectangles and around a point and Chandelles. At the conclusion of the last Chandelle, the engine sputtered in a way both pilots agreed was worrisome; indeed Emery mentioned that she'd never heard anything like that. However, the engine seemed to return to mostly normal, perhaps with a little underlying roughness. Mixture was full in the entire flight. Pilots agreed we should get to 2W5 airport, about 10nm away, but first ought gain some altitude as a precautionary measure, even asking for a Bravo clearance for same. ATC was contacted, no emergency was declared however permission was granted for a climb from 2500 to 4500 MSL.

With Cote at the controls we climbed to 4000' MSL on a heading of 340 direct to 2W5. Emery pulled carb heat and Cote agreed that was a good idea, the next several minuets in transit to 2W5 might have seen a small improvement in underlying roughness but it was a subtle change if any. Aircraft performed acceptably in the climb.

Upon arrival to 2W5 near the 02 runway at 4000', Cote lowered throttle rpm to 1500 and began a right-turning shallow circular descent. There was some discussion about which runway to land at, winds favored 20 but were light enough that either were acceptable. Despite searching, no traffic was seen in the pattern. CTAF was not dialed up. After one or two loops in descent, above a right downwind for runway 20 we were still at 1700' msl and above the airspeed acceptable for flaps (maybe 120mph). Cote and Emery discussed and agreed to Emery doing a slip to land Rwy 20 from a right base. Emery took the controls and executed the 180 turn starting abeam the numbers of Rwy 20 and sharply slipped into a rapid descent with left wing low, right rudder, pitched down. Flaps were not deployed. However, once on the centerline at midfield the plane remained 10' AGL and >100mph. Cote and Emery agreed to execute a go-around. Throttle went forward, carb heat off, engine advanced and the climb out began.

Around 300' AGL into the climbout, the Engine completely stopped. Cote futilely pulled out the carb heat. The only terrain ahead was solid trees. Emery factually stated "We are going into the trees." Cote concurred "We are going into the trees". Airspeed was maintained, wings stayed level, after a few seconds branches engaged in contact with the aircraft underbelly. The aircraft came to a halt in the tree canopy within a few seconds, teetered a brief moment, then pivoted engine first downward 70' to the ground. Contact was

RECOMMENDATION (How could this accident/incident have been prevented?)**Operator/Owner Safety Recommendation**

We are uncertain of the cause of the engine failure. Preventing engine failure would have prevented the accident.

If we had made a precautionary off-airport landing in one of the available fields en route to 2W5, a much safer landing would have occurred. That said, we had a working engine, so such a landing seems ill advised.

If the initial attempt to land had been better executed, the accident would have been prevented.

If we had elected not to go around and instead accepted running off the edge of the runway, a much safer landing would have occurred. That said, we had a working engine, so electing for a go around seemed reasonable at the time.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Engine failure

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

10 _____ Gallons

Fuel Type

☐ 80/87

☐ 115/145

☐ Jet B

☐ Other, specify _____

☒ 100 Low Lead

☐ Jet A

☐ JP8

☐ 100/130

☐ Jet A-1

☐ Automotive

Other Services, if Any, Prior to Departure

Fuel filled, tanks sumped immediately prior to flight.

EVACUATION OF AIRCRAFT

Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

Both pilots exited the right hand door. It was later observed that the left hand door was jammed shut

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed

☐ Minor

☐ Substantial

☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

02/19/2021

mm/dd/yyyy

Name of Pilot/Operator: Timothy Cote

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

ERA21LA132

Reviewed by NTSB Regional Office

AS-ERA

Name of Investigator

Lynn Spencer

Date Report Received

2/19/2021

Flight of N8428J Feb 17, 2021

N8428J is a Cessna 150 (C150) owned since June 2016 by Timothy Cote and intended as a trainer for himself to become a Certified Flight Instructor (CFI) and to teach aviation to teenagers. Timothy Cote employed Ms. Katrina Emery CFI to aid his preparation for the flight instructor rating. Timothy Cote is an instrument rated Commercial pilot with 838.5hr of flight time, of which only 21.9hrs are in the C150. Most of Cote's C150 hours (15.3) were accrued since the beginning of 2021, and the vast majority of these were accrued with Ms. Emery.

Prior to the events of Feb 17, the single most persistent sqwak in the plane was the repeated accumulation of water in the right wing. Mr Cote reported this to his A/P, Mr. Timothy Poole on the field at KVKX where the plane is based on a tie down, and Mr. Pool advised replacing the tank fill cap gaskets, which he did several weeks prior to Feb 17. Mr. Cote scrupulously sumped both tanks and the belly drain from the plane before each flight, and regularly rocked the wings to disrupt any water that might pool behind any wrinkle in either bladder tank. Subsequent to the gasket replacement, water was still sometimes found from the right tank or the belly drain however, it was relatively easy to clear this with repeated sumps.

On the morning of Feb 17 Mr Cote filled gas on both sides and sumped both tanks and the belly drain--the left tank had fuel only, the right tank had fuel only but dribbled slowly. At the belly drain, half the first tube was filled with water, however this disappeared and was fuel only in subsequent tube samples taken after 20sec of drainage. The wings were rocked, all drainage ports were retested and found to have only fuel without water contamination. Ms Emery was advised. The engine had 5 quarts of oil, above the minimum 4 quarts required. Other preflight operations were unremarkable.

Cote and Emery departed from KVKX, Cote in right seat, Emery in left. The first 60-90min of the flight were a collection of maneuvers in preparation for Cote's upcoming CFI checkride: Lazy 8s, turns around rectangles and around a point and Chandelles. At the conclusion of the last Chandelle, the engine sputtered in a way both pilots agreed was worrisome; indeed Emery mentioned that she'd never heard anything like that. However, the engine seemed to return to mostly normal, perhaps with a little underlying roughness. Mixture was full in the entire flight. Pilots agreed we should get to 2W5 airport, about 10nm away, but first ought gain some altitude as a precautionary measure, even asking for a Bravo clearance for same. ATC was contacted, no emergency was declared however permission was granted for a climb from 2500 to 4500 MSL.

With Cote at the controls we climbed to 4000' MSL on a heading of 340 direct to 2W5. Emery pulled carb heat and Cote agreed that was a good idea, the next several minuets in transit to 2W5 might have seen a small improvement in underlying roughness but it was a subtle change if any. Aircraft performed acceptably in the climb.

Upon arrival to 2W5 near the 02 runway at 4000', Cote lowered throttle rpm to 1500 and began a right-turning shallow circular descent. There was some discussion about which runway to land at, winds favored 20 but were light enough that either were acceptable. Despite searching, no traffic was seen in the pattern. CTAF was not dialed up. After one or two loops in descent, above a right downwind for runway 20 we were still at 1700' msl and above the airspeed acceptable for flaps (maybe 120mph). Cote and Emery discussed and agreed to Emery doing a slip to land Rwy 20 from a right base. Emery took the controls and executed the 180 turn starting abeam the numbers of Rwy 20 and sharply slipped into a rapid descent with left wing low, right rudder, pitched down. Flaps were not deployed. However, once on the centerline at midfield the plane remained 10' AGL and >100mph. Cote and Emery agreed to execute a go-around. Throttle went forward, carb heat off, engine advanced and the climb out began.

Around 300' AGL into the climbout, the Engine completely stopped. Cote futilely pulled out the carb heat. The only terrain ahead was solid trees. Emery factually stated "We are going into the trees." Cote concurred "We are going into the trees". Airspeed was maintained, wings stayed level, after a few seconds branches engaged in contact with the aircraft underbelly. The aircraft came to a halt in the tree canopy within a few seconds, teetered a brief moment, then pivoted engine first downward 70' to the ground. Contact was made with multiple branches along the way to the ground. After ground contact, Cote egressed via his right sided door and Emery follow him via that same door.

From: [tim.cote](#)
To: [Spencer Lynn](#)
Subject: Re: 6120 Questions
Date: Monday, February 22, 2021 3:37:36 PM

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Ms. Spencer,
Apologies for my errors on the form. Please see replies below:

On Mon, Feb 22, 2021 at 1:57 PM Spencer Lynn <[REDACTED]> wrote:

Good afternoon, Dr. Cote,

I have just a couple questions about your 6120.

1. Would you verify your single-engine flight hours on this matrix? Your entries may be reversed? (You show more SE PIC time than total SE time).

I do have 838 total hours, and 170 of these were multi engine. So my total in Single Engine should be 668. The number of those that were PIC depends on how PIC is counted. I have always presumed I was NOT PIC during my primary training, which was about 100 hours, making my SE PIC number more correctly 568.

However, that number reflects my presumption that I WAS PIC during my Instrument training (about 200hrs) as well as training for Seaplane, Commercial and CFI, each of which were about 30hrs and involved a CFI. Interestingly, in this accident I'm told that not I but Katrina was PIC based on some case law. Please advise.

1. Was this an IFR flight? You indicate that you filed an IFR flight plan but then you only selected "Traffic advisory" rather than IFR under your type of clearance.

This was not an IFR flight. It began as a FRZ flight out from KVKX and then was a simple VFR flight within the SFRA. After the plane first hiccupped, we called ATC to secure a Bravo clearance for a precautionary climb. We were given some traffic advisories along the way to 2W5.

Hope this is helpful.

Tim

1.