



Photo 1 – Airplane on jacks



Photo 2 – Left Horizontal stabilizer




Photo 3 – Left main landing gear down and lock actuator, leaking