



Photo 1 – View of Airplane as Found (AMF)



Photo 2 – View of Tail Section Right Wing and Engine Nacelle (AMF)



Photo 3 – View of Left Engine with Propeller Blades in Feathered Position (Lycoming)



Photo 4 – View of Right Engine and Curled Propeller Tip (Lycoming)



Photo 5 – View of Right Propeller Blade, Tip Curl, and Tear (Lycoming)



Photo 6 – Left Wing Gascolator as Found (Piper)



Photo 7 – Right Wing Gascolator with Occluded Debris Screen as Found (Piper)



Photo 8 – View of Duct Tape Strip Found Loose Inside Left Wing Inboard Fuel Cell (Piper)



Photo 9 – View of Duct Tape and Adhesive Residue on Left Inboard Fuel Tank Cap (Piper)



Photo 10 – Left Inboard Fuel Pick-up with Inlet Screen Not Installed (Piper)



Photo 11 – Right Wing Inboard Fuel Pick-up with Inlet Screen Installed (Piper)